

OIL ANALYSIS REPORT

Sample Rating Trend



CRANE #9

Component Main Gearbox Fluid MOBIL MOBILUBE HD 85W140 (--- GAL)

DIAGNOSIS

Recommendation

Resample at the next service interval to monitor. NOTE: Please provide information regarding reservoir capacity, filter type and micron rating with next sample.

Wear

All component wear rates are normal.

Contamination

There is no indication of any contamination in the oil.


Fluid Condition

The condition of the oil is acceptable for the time in service.

			Dec2022	Dec2023		
SAMPLE INFORM	IATION	method	limit/base	current	history1	history2
Sample Number		Client Info		WC0887217	WC0765207	
Sample Date		Client Info		09 Dec 2023	18 Dec 2022	
Machine Age	hrs	Client Info		0	0	
Oil Age	hrs	Client Info		0	0	
Oil Changed		Client Info		N/A	N/A	
Sample Status				NORMAL	NORMAL	
CONTAMINATION		method	limit/base	current	history1	history2
Water		WC Method	>0.2	NEG	NEG	
WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185(m)	>200	7	8	
Chromium	ppm	ASTM D5185(m)	>15	0	0	
Nickel	ppm	ASTM D5185(m)	>15	0	<1	
Titanium	ppm	ASTM D5185(m)		0	<1	
Silver	ppm	ASTM D5185(m)		0	0	
Aluminum	ppm	ASTM D5185(m)	>25	<1	1	
Lead	ppm	ASTM D5185(m)	>100	0	<1	
Copper	ppm	ASTM D5185(m)	>200	<1	<1	
Tin	ppm	ASTM D5185(m)	>25	0	<1	
Antimony	ppm	ASTM D5185(m)	>5	0	<1	
Vanadium	ppm	ASTM D5185(m)		0	0	
Beryllium	ppm	ASTM D5185(m)		0	0	
Cadmium	ppm	ASTM D5185(m)		0	0	
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185(m)		150	143	
Barium	ppm	ASTM D5185(m)		<1	<1	
Molybdenum	ppm	ASTM D5185(m)		0	0	
Manganese	ppm	ASTM D5185(m)		0	<1	
Magnesium	ppm	ASTM D5185(m)		<1	1	
Calcium	ppm	ASTM D5185(m)		15	14	
Phosphorus	ppm	ASTM D5185(m)		969	1000	
Zinc	ppm	ASTM D5185(m)		36	46	
Sulfur	ppm	ASTM D5185(m)		17358	16923	
Lithium	ppm	ASTM D5185(m)		3	3	
CONTAMINANTS		method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185(m)	>50	1	8	
Sodium	ppm	ASTM D5185(m)		2	7	
Potassium	ppm	ASTM D5185(m)	>20	1	<1	



OIL ANALYSIS REPORT



history1	history2
NONE	
NORML	
NORML	
NEG	
NEG	
history1	history2
299	
history1	history2
	no image
	no image
tinuous Colou	
1430 N	Aartin Grove R Rexdale, O
	CA M9W 4Y
	arminder Sing
er.s	

Validity of results and interpretation are based on the sample and information as supplied.

Contact/Location: Parminder Singh - METREX

F: (416)743-7138