

OIL ANALYSIS REPORT

Extrudex Alum - E00400 A2312108

Component **Hydraulic System**

AW HYDRAULIC OIL ISO 68 (--- GAL)



Recommendation

This is a baseline read-out on the submitted sample.

Wear

Aluminum, copper and iron ppm levels are noted.

Contamination

{not applicable}

Fluid Condition

{not applicable}

				Dec2023		
SAMPLE INFORM	MATION	method	limit/base	current	history1	history2
Batch #		Client Info		2023 12 0360		
Department		Client Info		Production		
Sample From		Client Info		Machine		
Production Stage		Client Info		Initial		
Sent to WC		Client Info		12/21/2023		
Sample Number		Client Info		E30001029		
Sample Date		Client Info		21 Dec 2023		
Machine Age	hrs	Client Info		0		
Oil Age	hrs	Client Info		0		
Oil Changed		Client Info		N/A		
Sample Status				NORMAL		
CONTAMINATION	V	method	limit/base	current	history1	history2
	N .				Thistory	HISTOTYZ
Water		WC Method	>0.05	NEG		
WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185(m)	>20	65		
Chromium	ppm	ASTM D5185(m)	>10	<1		
Nickel	ppm	ASTM D5185(m)	>10	<1		
Titanium	ppm	ASTM D5185(m)		0		
Silver	ppm	ASTM D5185(m)		0		
Aluminum	ppm	ASTM D5185(m)	>10	13		
Lead	ppm	ASTM D5185(m)	>20	8		
Copper	ppm	ASTM D5185(m)	>20	75		
Tin	ppm	ASTM D5185(m)	>10	1		
Antimony	ppm	ASTM D5185(m)		0		
Vanadium	ppm	ASTM D5185(m)		0		
Beryllium	ppm	ASTM D5185(m)		0		
Cadmium	ppm	ASTM D5185(m)		0		
ADDITIVES		method	limit/base	current	history1	history2
Boron	nnm	ASTM D5185(m)		2		
	ppm	. ,	5			
Barium	ppm	ASTM D5185(m)		<1		
Molybdenum	ppm	ASTM D5185(m)	5	0		
Manganese	ppm	ASTM D5185(m)	O.F.	<1		
Magnesium	ppm	ASTM D5185(m)	25	19 77		
Calcium	ppm	ASTM D5185(m)	200	77		
Phosphorus	ppm	ASTM D5185(m)	300	574		
Zinc	ppm	ASTM D5185(m)	370	440		
Sulfur	ppm	ASTM D5185(m)	2500	1892		
Lithium	ppm	ASTM D5185(m)		<1		
CONTAMINANTS		method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185(m)	>15	7		
Sodium	ppm	ASTM D5185(m)		2		
Potassium	ppm	ASTM D5185(m)	>20	1		



OIL ANALYSIS REPORT

VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	Visual*	NONE	NONE		
Yellow Metal	scalar	Visual*	NONE	NONE		
Precipitate	scalar	Visual*	NONE	LIGHT		
Silt	scalar	Visual*	NONE	NONE		
Debris	scalar	Visual*	NONE	NONE		
Sand/Dirt	scalar	Visual*	NONE	VLITE		
Appearance	scalar	Visual*	NORML	NORML		
Odor	scalar	Visual*	NORML	NORML		
SAMPLE IMAGES	;	method	limit/base	current	history1	history2
Color					no image	no image
Bottom					no image	no image
GRAPHS						



CALA ISO 17025:2017 Accredited Laboratory

Laboratory Sample No.

Lab Number

: 02605140 Unique Number : 5698225

: WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9 : E30001029 Recieved Diagnosed Test Package : TEST (Additional Tests: Bottom, ICP)

: 22 Dec 2023 : 02 Jan 2024 Diagnostician : Tatiana Sorkina

To discuss this sample report, contact Customer Service at 1-905-372-2251.

Cobourg, ON CA K9A 5H5 Contact: Tatiana Sorkina tsorkina@e360s.ca Test denoted (*) outside scope of accreditation, (m) method modified, (e) tested at external lab. T: (800)263-3939 Validity of results and interpretation are based on the sample and information as supplied. F: (905)373-4950

Environmental 360 Solutions Ltd.

640 Victoria Street