


FUEL REPORT

Area [99923] Machine Id PENTHOUSE

Component

1 Diesel Fuel

No.2 DIESEL FUEL (LOW-SULPHUR) (--- GAL)



DIAGNOSIS

Recommendation

Check seals and/or filters for points of contaminant entry. Laboratory test indicate that this fuel is suitable for use and meets all test requirements. The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather. We advise that you filter this fluid before use. We recommend you service the filters on this component. Resample in 30-45 days to monitor this situation.

Corrosion

{not applicable}

Contaminants

There is a high amount of silt (particulates < 14 microns in size) present in the fuel. The water content is negligible.


Fuel Condition

All laboratory tests indicate that this sample meets specifications for No.2 diesel fuel, low sulfur (US EPA/CGSB-3.517-3 type B). The fuel is still serviceable provided that the contaminant(s) can be reduced to acceptable levels.

iAL)				Dec2023		
SAMPLE INFORM	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		CU0020769		
Sample Date		Client Info		16 Dec 2023		
Machine Age	hrs	Client Info		0		
Sample Status				SEVERE		
PHYSICAL PROP	ERTIES	method	limit/base	current	history1	history2
Specific Gravity		ASTM D1298*	0.839	0.829		
Fuel Color	text	Visual Screen*	Yllow	DkGry		
Visc @ 40°C	cSt	ASTM D7279(m)	3.0	2.2		
Pensky-Martens Flash Point	°C	ASTM D7215*	52	54.8		
SULFUR CONTE	NT	method	limit/base	current	history1	history2
Sulfur	ppm	ASTM D5185(m)	250	23		
DISTILLATION		method	limit/base	current	history1	history2
Initial Boiling Point	°C	ASTM D2887*	165	164		
5% Distillation Point	°C	ASTM D2887*		186		
10% Distill Point	°C	ASTM D2887*	201	195		
15% Distillation Point	°C	ASTM D2887*		202		
20% Distill Point	°C	ASTM D2887*	216	210		
30% Distill Point	°C	ASTM D2887*	230	224		
40% Distill Point	°C	ASTM D2887*	243	237		
50% Distill Point	°C	ASTM D2887*	255	250		
60% Distill Point	°C	ASTM D2887*	267	265		
70% Distill Point	°C	ASTM D2887*	280	279		
80% Distill Point	°C	ASTM D2887*	295	294		
85% Distillation Point	°C	ASTM D2887*		306		
90% Distill Point	°C	ASTM D2887*	310	317		
95% Distillation Point	°C	ASTM D2887*		337		
Final Boiling Point	°C	ASTM D2887*	341	372		
IGNITION QUALIT	ΓΥ	method	limit/base	current	history1	history2
API Gravity		ASTM D1298*	37.7	39		
Cetane Index		ASTM D4737*	<40.0	50		
CONTAMINANTS		method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185(m)	<1.0	0		
Sodium	ppm	ASTM D5185(m)	< 0.1	<1		
Potassium	ppm	ASTM D5185(m)	<0.1	0		
Water	%	ASTM D6304*	< 0.05	0.00		
ppm Water	ppm	ASTM D6304*	<500	0		
FLUID CLEANLIN	ESS	method	limit/base	current	history1	history2
Particles >4µm		ASTM D7647	>2500	52398		
Particles >6µm		ASTM D7647	>640	<u>^</u> 2605		
Particles >14µm		ASTM D7647	>80	9		
Particles >21µm		ASTM D7647	>20	2		
Particles >38µm		ASTM D7647	>4	0		
Particles >71µm		ASTM D7647	>3	0		
Oil Cleanliness		ISO 4406 (c)	>18/16/13	23/19/10		



FUEL REPORT





CALA ISO 17025:2017 Accredited

Laboratory

Laboratory Sample No. Lab Number **Unique Number**

: WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9 : CU0020769

: 02607622

Recieved Diagnosed : 5708708

: 12 Jan 2024 Diagnostician : Kevin Marson

: 09 Jan 2024

Test Package : FUEL (Additional Tests: CC Flash, GC-PercFuel, PrtCount)

To discuss this sample report, contact Customer Service at 1-800-268-2131. Test denoted (*) outside scope of accreditation, (m) method modified, (e) tested at external lab. Validity of results and interpretation are based on the sample and information as supplied.

CUMMINS EASTERN CANADA LP 315 AV LIBERTE

CANDIAC, QC **CA J5R 6Z7**

Contact: Service Manager

F: (450)638-6731

T: