


OIL ANALYSIS REPORT

Goodyear - G04000 **A2401078**

Component **Hydraulic System**

AW HYDRAULIC OIL ISO 68 (--- GAL)



DIAGNOSIS

Recommendation

This is a baseline read-out on the submitted sample.

Wear

Copper, iron and lead ppm levels are noted.

Contamination

Water and ppm water contamination levels are abnormal. Silicon ppm levels are notably high.

Fluid Condition

{not applicable}

				Jan 2024		
SAMPLE INFORM	MATION	method	limit/base	current	history1	history2
Batch #		Client Info		2024 01 0160		
Department		Client Info		Production		
Sample From		Client Info		Machine		
Production Stage		Client Info		Initial		
Sent to WC		Client Info		01/15/2024		
Sample Number		Client Info		E30001155		
Sample Date		Client Info		15 Jan 2024		
Machine Age	hrs	Client Info		0		
Oil Age	hrs	Client Info		0		
Oil Changed		Client Info		N/A		
Sample Status				SEVERE		
WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185(m)	>20	37		
Chromium	ppm	ASTM D5185(m)	>10	<1		
Nickel	ppm	ASTM D5185(m)	>10	1		
Titanium	ppm	ASTM D5185(m)		0		
Silver	ppm	ASTM D5185(m)		<1		
Aluminum	ppm	ASTM D5185(m)	>10	5		
Lead	ppm	ASTM D5185(m)	>20	13		
Copper	ppm	ASTM D5185(m)	>20	97		
Tin	ppm	ASTM D5185(m)	>10	<1		
Antimony	ppm	ASTM D5185(m)		0		
Vanadium	ppm	ASTM D5185(m)		0		
Beryllium	ppm	ASTM D5185(m)		0		
Cadmium	ppm	ASTM D5185(m)		0		
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185(m)	5	2		
Barium	ppm	ASTM D5185(m)	5	<1		
Molybdenum	ppm	ASTM D5185(m)	5	0		
Manganese	ppm	ASTM D5185(m)		<1		
Magnesium	ppm	ASTM D5185(m)	25	7		
Calcium	ppm	ASTM D5185(m)	200	43		
Phosphorus	ppm	ASTM D5185(m)	300	563		
Zinc	ppm	ASTM D5185(m)	370	425		
Sulfur	ppm	ASTM D5185(m)	2500	2014		
Lithium	ppm	ASTM D5185(m)		<1		
CONTAMINANTS	;	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185(m)	>15	11		

Sodium

Water

Potassium

ppm Water

ppm

ppm

ppm

%

ASTM D5185(m)

ASTM D5185(m) >20

ASTM D6304* >0.05

ASTM D6304* >500


1

2.198

21983



OIL ANALYSIS REPORT



VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	Visual*	NONE	NONE		
Yellow Metal	scalar	Visual*	NONE	NONE		
Precipitate	scalar	Visual*	NONE	NONE		
Silt	scalar	Visual*	NONE	NONE		
Debris	scalar	Visual*	NONE	NONE		
Sand/Dirt	scalar	Visual*	NONE	NONE		
Appearance	scalar	Visual*	NORML	MILKY		
Odor	scalar	Visual*	NORML	NORML		

SAMPLE IMAGES	metnod	ilmit/base	current	nistory i	nistory2
Color				no image	no image
Bottom				no image	no image
GRAPHS					



CALA ISO 17025:2017 Accredited Laboratory

Laboratory Sample No. Lab Number Unique Number : 5710660

: WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9 : E30001155 : 02609574

Recieved Diagnosed : 17 Jan 2024 : 19 Jan 2024

Test Package : TEST (Additional Tests: ICP, KF)

Diagnostician : Tatiana Sorkina

Cobourg, ON CA K9A 5H5 Contact: Tatiana Sorkina tsorkina@e360s.ca T: (800)263-3939 F: (905)373-4950

640 Victoria Street

Environmental 360 Solutions Ltd.

To discuss this sample report, contact Customer Service at 1-905-372-2251.

Test denoted (*) outside scope of accreditation, (m) method modified, (e) tested at external lab. Validity of results and interpretation are based on the sample and information as supplied.