

OIL ANALYSIS REPORT

Sample Rating Trend

CONTAMINANT



Gary Steacy - G02900 A2401079

Component

{not provided} (--- GAL)

Transformer Oil

DIAGNOSIS

Recommendation

PCB is between 2.0 and 5.0

Cumpi	o maning mond		
			1
*			
			_
	Jan 202	4	-
method	limit/base	current	hist

SAMPLE INFORM	MATION	method	limit/base	current	history1	history2
Batch #		Client Info		2024 01 0180		
Department		Client Info		Production		
Sample From		Client Info		Machine		
Production Stage		Client Info		Initial		
Sent to WC		Client Info		01/15/2024		
Sample Number		Client Info		E30001156		
Sample Date		Client Info		15 Jan 2024		
Machine Age	hrs	Client Info		0		
Oil Age	hrs	Client Info		0		
Oil Changed		Client Info		N/A		
Sample Status				ABNORMAL		
CONTAMINATION	١	method	limit/base	current	history1	history2
Water		WC Method	>0.0035	NEG		
WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185(m)	>125	0		
Chromium	ppm	ASTM D5185(m)		0		
Nickel	ppm	ASTM D5185(m)		<1		
Titanium	ppm	ASTM D5185(m)		0		
Silver	ppm	ASTM D5185(m)	>2	0		
Aluminum	ppm	ASTM D5185(m)	>5	<1		
Lead	ppm	ASTM D5185(m)	>30	0		
Copper	ppm	ASTM D5185(m)	>10	<1		
Tin	ppm	ASTM D5185(m)	>2	0		
Antimony	ppm	ASTM D5185(m)		0		
Vanadium	ppm	ASTM D5185(m)		0		
Beryllium	ppm	ASTM D5185(m)		0		
Cadmium	ppm	ASTM D5185(m)		0		
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185(m)		0		
Barium	ppm	ASTM D5185(m)		0		
Molybdenum	ppm	ASTM D5185(m)		0		
Manganese	ppm	ASTM D5185(m)		0		
Magnesium	ppm	ASTM D5185(m)		<1		
Calcium	ppm	ASTM D5185(m)		<1		
Phosphorus	ppm	ASTM D5185(m)		<1		
Zinc	ppm	ASTM D5185(m)		1		
Sulfur	ppm	ASTM D5185(m)		1274		
Lithium	ppm	ASTM D5185(m)		<1		
CONTAMINANTS		method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185(m)	>25	<1		
Sodium	ppm	ASTM D5185(m)		0		
Potassium	ppm	ASTM D5185(m)	>20	1		
PCBs	ppm	EPA 8082(e)*		<u>^</u> 2.8		



OIL ANALYSIS REPORT

VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	Visual*	NONE	NONE		
Yellow Metal	scalar	Visual*	NONE	NONE		
Precipitate	scalar	Visual*	NONE	NONE		
Silt	scalar	Visual*	NONE	NONE		
Debris	scalar	Visual*	NONE	NONE		
Sand/Dirt	scalar	Visual*	NONE	NONE		
Appearance	scalar	Visual*	NORML	NORML		
Odor	scalar	Visual*	NORML	NORML		
SAMPLE IMAGE	ES	method	limit/base	current	history1	history2
Color					no image	no image
Bottom					no image	no image
GRAPHS						
Dielectric BDV			10	Interfacial Te	nsion	
10			10			
8 +			8	† :		
6+			6	1		
4			<u></u> 4	†		
2			Interfacial Tension (mlVm)			
0			0 88	-		
-2			-2			
4			Interfer			
-6						
1			-6			
-8 🕇						
10 + 52			-10			- 42
Jan 15/24			Jan15/24	Jan 15/24		Jan15/24
iii			- i	¬		7



ISO 17025:2017
Accredited
Laboratory

Laboratory : WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9

Sample No. : E30001156 Received : 17 Jan 2024
Lab Number : 02609575 Tested : 19 Jan 2024
Unique Number : 5710661 Diagnosed : 27 Mar 2024 - Tatiana Sorkina

Test Package: TEST (Additional Tests: ICP, PCBTransformer)

To discuss this sample report, contact Customer Service at 1-905-372-2251.

Test denoted (*) outside scope of accreditation, (m) method modified, (e) tested at external lab. Validity of results and interpretation are based on the sample and information as supplied.

Environmental 360 Solutions Ltd.

640 Victoria Street Cobourg, ON CA K9A 5H5

Contact: Tatiana Sorkina tsorkina@e360s.ca T: (800)263-3939 F: (905)373-4950