

OIL ANALYSIS REPORT

Alcoa Howmet - H01900 A2401092

Component

Unknown Component

{not provided} (--- GAL)

Sample Rating Trend



	SAMPLE INFORMA	NOITA	method	limit/base	current	history1	history2
	Batch #		Client Info		2024 01 0230		
the submitted	Department		Client Info		Production		
	Sample From		Client Info		Machine		
	Production Stage		Client Info		Initial		
	Sent to WC		Client Info		01/18/2024		
	Sample Number		Client Info		E30001203		
	Sample Date		Client Info		17 Jan 2024		
	Machine Age	hrs	Client Info		0		
high.	Oil Age	hrs	Client Info		0		
	Oil Changed		Client Info		N/A		
	Sample Status				ATTENTION		

Sample Status				ATTENTION		
CONTAMINATIO	N	method	limit/base	current	history1	history2
Water		WC Method		NEG		
WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185(m)		6		
Chromium	ppm	ASTM D5185(m)		0		
Nickel	ppm	ASTM D5185(m)		<1		
Titanium	ppm	ASTM D5185(m)		0		
Silver	ppm	ASTM D5185(m)		0		
Aluminum	ppm	ASTM D5185(m)		1		
Lead	ppm	ASTM D5185(m)		<1		
Copper	ppm	ASTM D5185(m)		9		
Tin	ppm	ASTM D5185(m)		0		
Antimony	ppm	ASTM D5185(m)		0		
Vanadium	ppm	ASTM D5185(m)		0		
Beryllium	ppm	ASTM D5185(m)		0		
Cadmium	ppm	ASTM D5185(m)		0		
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185(m)		3		
Barium	ppm	ASTM D5185(m)		0		
Molybdenum	ppm	ASTM D5185(m)		0		
Manganese	ppm	ASTM D5185(m)		0		
Magnesium	ppm	ASTM D5185(m)		5		
Calcium	ppm	ASTM D5185(m)		220		
Phosphorus	ppm	ASTM D5185(m)		7		
Zinc	ppm	ASTM D5185(m)		8		
Sulfur	ppm	ASTM D5185(m)		1089		
Lithium	ppm	ASTM D5185(m)		2		
CONTAMINANTS	;	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185(m)		2		
Sodium	ppm	ASTM D5185(m)		▲ 399		
Potassium	ppm	ASTM D5185(m)	>20	10		

▲ Recommendation

This is a baseline read-out on th sample.

Wear

{not applicable}

Contamination


{not applicable}

▲ Fluid Condition

Sodium ppm levels are notably



OIL ANALYSIS REPORT



VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	Visual*	NONE	NONE		
Yellow Metal	scalar	Visual*	NONE	NONE		
Precipitate	scalar	Visual*	NONE	NONE		
Silt	scalar	Visual*	NONE	LIGHT		
Debris	scalar	Visual*	NONE	NONE		
Sand/Dirt	scalar	Visual*	NONE	NONE		
Appearance	scalar	Visual*	NORML	NORML		
Odor	scalar	Visual*	NORML	NORML		
SAMPLE IMAGES	;	method	limit/base	current	history1	history2
Color			i		no image	no image
Bottom					no image	no image
GRAPHS						



CALA ISO 17025:2017 Accredited Laboratory

Laboratory Sample No. Lab Number

: WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9

: E30001203 : 02610485

Unique Number : 5711571 Test Package : TEST (Additional Tests: ICP)

Recieved : 22 Jan 2024 : 24 Jan 2024 Diagnosed

Diagnostician : Tatiana Sorkina

Cobourg, ON CA K9A 5H5 Contact: Tatiana Sorkina tsorkina@e360s.ca T: (800)263-3939 F: (905)373-4950

640 Victoria Street

Environmental 360 Solutions Ltd.

To discuss this sample report, contact Customer Service at 1-905-372-2251. Test denoted (*) outside scope of accreditation, (m) method modified, (e) tested at external lab.

Validity of results and interpretation are based on the sample and information as supplied.