


Sample Rating Trend



NORMAL



Area
PERIMETER AVIATION [53083]
 Machine Id
METRO III SA 227 AC P-44180C
 Component
Jet Turbine
 Fluid
EASTMAN TURBO OIL 2380 (--- GAL)

DIAGNOSIS



Recommendation

This is a baseline read-out on the submitted sample.

SAMPLE INFORMATION		method	limit/base	current	history1	history2
Sample Number	Client Info			GT57791	GT55550	GT53694
Sample Date	Client Info			15 Mar 2024	23 Jun 2022	10 May 2021
Machine Age	hrs	Client Info		0	0	0
Oil Age	hrs	Client Info		248	154	867
Oil Changed	Client Info			N/A	N/A	N/A
Sample Status				NORMAL	NORMAL	---

CONTAMINATION		method	limit/base	current	history1	history2
Water	WC Method		>0.1	NEG	NEG	NEG

SAMPLE IMAGES		method	limit/base	current	history1	history2
---------------	--	--------	------------	---------	----------	----------

Color					no image	no image
Bottom					no image	no image

OIL ANALYSIS REPORT

GRAPHS



ISO 17025:2017
Accredited
Laboratory

Laboratory : WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9
Sample No. : GT57791
Lab Number : 02622935
Unique Number : 5748054
Test Package : TEST

Received : 18 Mar 2024
Tested : 18 Mar 2024
Diagnosed : 18 Mar 2024 - Wes Davis

Honeywell Engines
111 S. 34th Street, 301 Receiving, Attn: SOAP Program
PHOENIX, AZ
US 85034
Contact: GARRETT

*To discuss this sample report, contact Customer Service at 1-800-268-2131.
Test denoted (*) outside scope of accreditation, (m) method modified, (e) tested at external lab.
Validity of results and interpretation are based on the sample and information as supplied.*

T:
F: (602)365-2676