



OIL ANALYSIS REPORT


Sample Rating Trend

NORMAL



Machine Id PROJECT DELAWARE CLEAN ROOM TETING GROUP 4

Component
Unknown Component
Fluid
{not provided} (--- GAL)



DIAGNOSIS

Recommendation

This is a baseline read-out on the submitted sample.

Contamination

ISO Cleanliness Code (ISO 4406:1999): 22/20/15;
Cumulative particle counts >4µm = 26447, >6µm = 7205, >14µm = 288, >21µm = 38, >38µm = 3, >71µm = 0.

SAMPLE INFORMATION

	method	limit/base	current	history1	history2
Sample Number	Client Info		WC0916387	---	---
Sample Date	Client Info		25 Mar 2024	---	---
Machine Age	hrs	Client Info	0	---	---
Oil Age	hrs	Client Info	0	---	---
Oil Changed	Client Info		N/A	---	---
Sample Status			NORMAL	---	---

CONTAMINATION

	method	limit/base	current	history1	history2
Water	WC Method		NEG	---	---

FLUID CLEANLINESS

	method	limit/base	current	history1	history2
Particles >4µm	ASTM D7647	>5000	26447	---	---
Particles >6µm	ASTM D7647	>1300	7205	---	---
Particles >14µm	ASTM D7647	>160	288	---	---
Particles >21µm	ASTM D7647	>40	38	---	---
Particles >38µm	ASTM D7647	>10	3	---	---
Particles >71µm	ASTM D7647	>3	0	---	---
Oil Cleanliness	ISO 4406 (c)	>19/17/14	22/20/15	---	---

VISUAL


	method	limit/base	current	history1	history2	
White Metal	scalar	Visual*	NONE	NONE	---	---
Yellow Metal	scalar	Visual*	NONE	NONE	---	---
Precipitate	scalar	Visual*	NONE	NONE	---	---
Silt	scalar	Visual*	NONE	NONE	---	---
Debris	scalar	Visual*	NONE	VLITE	---	---
Sand/Dirt	scalar	Visual*	NONE	NONE	---	---
Appearance	scalar	Visual*	NORML	NORML	---	---
Odor	scalar	Visual*	NORML	NORML	---	---

SAMPLE IMAGES

	method	limit/base	current	history1	history2
Color				no image	no image
Bottom				no image	no image

OIL ANALYSIS REPORT

GRAPHS



Laboratory : WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9
Sample No. : WC0916387
Lab Number : 02624785
Unique Number : 5749904
Test Package : TEST (Additional Tests: PrtCount)

Received : 26 Mar 2024
Tested : 27 Mar 2024
Diagnosed : 27 Mar 2024 - Kevin Marson

Horstman
 110 East Drive
 Brampton, ON
 CA L6T 1C1

Contact: Christine Albecker
 Christine.Albecker@horstmancanada.com
 T: (905)458-0188

To discuss this sample report, contact Customer Service at 1-800-268-2131.
 Test denoted (*) outside scope of accreditation, (m) method modified, (e) tested at external lab.
 Validity of results and interpretation are based on the sample and information as supplied.