







# CLEANLINESS TEST REPORT



## GRAPHS



**Laboratory** : WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9  
**Sample No.** : WC0928220 **Received** : 28 Mar 2024  
**Lab Number** : 02625108 **Tested** : 28 Mar 2024  
**Unique Number** : 5750227 **Diagnosed** : 28 Mar 2024 - Bill Quesnel  
**Test Package** : TEST ( Additional Tests: PrtCount, PrtFilter, PrtFilterPic )

**PARKER HANNIFIN CANADA**  
 160 CHISHOLM DRIVE  
 MILTON, ON  
 CA L9T 3G9  
 Contact: Walter Wozniak  
 walter.wozniak@parker.com  
 T: (905)693-3000  
 F:

To discuss this sample report, contact Customer Service at 1-800-268-2131.  
 Test denoted (\*) outside scope of accreditation, (m) method modified, (e) tested at external lab.  
 Validity of results and interpretation are based on the sample and information as supplied.