






CLEANLINESS TEST REPORT



GRAPHS



Laboratory : WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9
Sample No. : WC0928221 **Received** : 28 Mar 2024
Lab Number : 02625109 **Tested** : 28 Mar 2024
Unique Number : 5750228 **Diagnosed** : 28 Mar 2024 - Bill Quesnel
Test Package : TEST (Additional Tests: PrtCount, PrtFilter, PrtFilterPic)

PARKER HANNIFIN CANADA
 160 CHISHOLM DRIVE
 MILTON, ON
 CA L9T 3G9
 Contact: Tom Raznatovic
 tomislav.raznatovic@parker.com

To discuss this sample report, contact Customer Service at 1-800-268-2131.
 Test denoted (*) outside scope of accreditation, (m) method modified, (e) tested at external lab.
 Validity of results and interpretation are based on the sample and information as supplied.

T:
F: