# OIL ANALYSIS REPORT

**Sample Rating Trend**

Mar2024

**NORMAL**

✓

Machine Id
## SAW SAVE 100 (B2)
Component
**Unknown Component**
Fluid
**{not provided} (--- GAL)**

| DIAGNOSIS |
|---|

**Recommendation**
This is a baseline read-out on the submitted sample.

**Fluid Condition**
Pour Point = -36°C.

| SAMPLE INFORMATION | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|
| Sample Number | | Client Info | **PP** | --- | --- |
| Sample Date | | Client Info | **31 Mar 2024** | --- | --- |
| Machine Age | hrs | Client Info | **0** | --- | --- |
| Oil Age | hrs | Client Info | **0** | --- | --- |
| Oil Changed | | Client Info | **N/A** | --- | --- |
| Sample Status | | | **NORMAL** | --- | --- |

| CONTAMINATION | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|
| Water | | WC Method | **NEG** | --- | --- |

| VISUAL | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| White Metal | scalar | Visual* | NONE | **NONE** | --- | --- |
| Yellow Metal | scalar | Visual* | NONE | **NONE** | --- | --- |
| Precipitate | scalar | Visual* | NONE | **NONE** | --- | --- |
| Silt | scalar | Visual* | NONE | **NONE** | --- | --- |
| Debris | scalar | Visual* | NONE | **NONE** | --- | --- |
| Sand/Dirt | scalar | Visual* | NONE | **NONE** | --- | --- |
| Appearance | scalar | Visual* | NORML | **NORML** | --- | --- |
| Odor | scalar | Visual* | NORML | **NORML** | --- | --- |

| FLUID PROPERTIES | | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|---|
| Pour Point | °C | ASTM D97* | | **-36** | --- | --- |

| SAMPLE IMAGES | method | limit/base | current | history1 | history2 |
|---|---|---|---|---|---|
| Color | | |  | no image | no image |
| Bottom | | |  | no image | no image |

GRAPHS