

FILTER DEBRIS ANALYSIS

Area Filter 5-3-241 Flender High Pressure Pump Component Filter

Fluid {not provided} (--- GAL)

DIAGNOSIS

Recommendation


Resample at the next service interval to monitor. Please specify the brand, type, and viscosity of the oil on your next sample.

Wear Particles

The filter contained no appreciable wear particles. All filter wear levels are normal.

Contaminants

The filter contained only normal levels of contaminants, and debris. All filter contaminant levels are normal.



Sample Rating Trend

SAMPLE INFORM	1ATION	method	limit/base	current	history1	history2
Sample Number		Client Info		PP	WC944775	WC975738
Sample Date		Client Info		14 Apr 2024	10 Apr 2018	02 Nov 2016
Machine Age	hrs	Client Info		0	0	0
Oil Age	hrs	Client Info		0	0	0
Oil Changed		Client Info		N/A	Changed	N/A
Sample Status				NORMAL	NORMAL	NORMAL
CONTAMINATION	١	method	limit/base	current	history1	history2
Water		WC Method		NEG	NEG	NEG
FILTER WEAR PAP	RTICLES	method	limit/base	current	history1	history2
Ferrous Rubbing	Scale 0-10	ASTM D7684*		1	2	2
Ferrous Sliding	Scale 0-10	ASTM D7684*				
Ferrous Cutting	Scale 0-10	ASTM D7684*				
Ferrous Rolling	Scale 0-10	ASTM D7684*			1	1
Ferrous Break-in	Scale 0-10	ASTM D7684*				
Ferrous Spheres	Scale 0-10	ASTM D7684*				
Ferrous Black Oxides	Scale 0-10	ASTM D7684*				
Ferrous Red Oxides	Scale 0-10	ASTM D7684*				
Ferrous Corrosive	Scale 0-10	ASTM D7684*				
Ferrous Other	Scale 0-10	ASTM D7684*				
Nonferrous Rubbing	Scale 0-10	ASTM D7684*		1		
Nonferrous Sliding	Scale 0-10	ASTM D7684*				
Nonferrous Cutting	Scale 0-10	ASTM D7684*				
Nonferrous Rolling	Scale 0-10	ASTM D7684*		1		
Nonferrous Other	Scale 0-10	ASTM D7684*				
FILTER CONTAM	INANTS	method	limit/base	current	history1	history2
Sand/Dirt	Scale 0-10	ASTM D7684*		2	2	1
Fibres	Scale 0-10	ASTM D7684*		1	1	
Spheres	Scale 0-10	ASTM D7684*				
Other	Scale 0-10	ASTM D7684*			2	2
Patch Weight	mg	ASTM D7684*		44	58	32
SAMPLE IMAGES	;	method	limit/base	current	history1	history2
Color				no image	no image	no image
Bottom				no image	no image	no image



FILTER REPORT

Area Filter Machine To 5-3-241 Flender High Pressure Pump Component Filter Fluid

{not provided} (--- GAL)





WEAR

The filter contained no appreciable wear particles. All filter wear levels are normal.