[[01-26544]] MERCRUISER OL393568 - PORT DIESEL ENGINE

Sample No: WA0019417
Oil Type: SIERRA 25W40

Zinc

Barium

Boron

Phosphorus

SAMPLE INF	ORMATION	N			
Sample Number		WA0019417			
Sample Date		12 Apr 2024			
Machine Hours		1003			
Oil Hours		100			
Oil Changed		Changed			
Sample Status		NORMAL			
	TION				
OIL CONDI	HON				
Visc @ 100°C	cSt	13.2			
Base Number (BN)	mg KOH/g	6.44			
Oxidation (PA)	%	40			
CONTAMINATION					
		NEC			
Water	%	NEG			
Soot %	%	■ 0 58			
Nitration (PA) Sulfation (PA)	%	51			
	%	NEG			
Glycol	%	<1.0			
Silicon		□14			
Sodium	ppm	■ 14 ■ 16			
Potassium	ppm	■ 2			
	ppm	<u> </u>			
WEAR METALS					
Iron	ppm	16			
Copper	ppm	23			
Lead	ppm	1			
Tin	ppm				
Aluminum	ppm	■ 3			
Chromium	ppm	■<1			
Molybdenum	ppm	10			
Nickel	ppm	■<1			
Titanium	ppm	<1			
Silver	ppm	■ 0			
Manganese	ppm	<1			
Vanadium	ppm	0			
ADDITIVES					
		= 2010			
Calcium	ppm	□ 2010			
Magnesium	ppm	20			

08:32:04) Rev: 1

945

765

0

26

ppm

ppm

ppm

l ppm

CHANTIER BLYACHT

1225 BOUL. CHAMPLAIN QUEBEC, QC CA G1K 0A2 Contact: Service Manager rboulet@chantierblyacht.com T: (514)961-2206 F:

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is suitable for further service.

Depot: CHA122QUE
Unique No: 5763172
Signed: Kevin Marson
Report Date: 19 Apr 2024
Contact/Location: Service Manager - CHA122QUE

