

FILTER DEBRIS ANALYSIS

Sample Rating Trend



Machine Id

LAND ROVER 24090

Component Filter Fluid {not provided} (--- GAL)

DIAGNOSIS

Recommendation

We understand that this sample is for warranty/insurance purposes. Diagnostician's Note:

There were a slightly abnormal quantity of ferrous sliding wear particles present in the filter. The particles showed no signs of tempering (lack of lubrication). There were no abnormal contaminants present in the filter.

Wear Particles

The filter contained a light concentration of ferrous sliding wear particles. All other component wear rates are normal.

Contaminants

The filter contained only normal levels of contaminants, and debris. All filter contaminant levels are normal.


SAMPLE INFORM	IATION	method	limit/base	current	history1	history2
Sample Number		Client Info		PP0001444		
Sample Date		Client Info		11 Jun 2024		
Machine Age	hrs	Client Info		0		
Oil Age	hrs	Client Info		0		
Oil Changed		Client Info		N/A		
Sample Status				NORMAL		
CONTAMINATION	J	method	limit/base	current	history1	history2
Water		WC Method		NEG		
FILTER WEAR PAP	RTICLES	method	limit/base	current	history1	history2
Ferrous Rubbing	Scale 0-10	ASTM D7684*		2		
Ferrous Sliding	Scale 0-10	ASTM D7684*		2		
Ferrous Cutting	Scale 0-10	ASTM D7684*				
Ferrous Rolling	Scale 0-10	ASTM D7684*		1		
Ferrous Break-in	Scale 0-10	ASTM D7684*				
Ferrous Spheres	Scale 0-10	ASTM D7684*				
Ferrous Black Oxides	Scale 0-10	ASTM D7684*				
Ferrous Red Oxides	Scale 0-10	ASTM D7684*				
Ferrous Corrosive	Scale 0-10	ASTM D7684*				
Ferrous Other	Scale 0-10	ASTM D7684*				
Nonferrous Rubbing	Scale 0-10	ASTM D7684*		2		
Nonferrous Sliding	Scale 0-10	ASTM D7684*				
Nonferrous Cutting	Scale 0-10	ASTM D7684*				
Nonferrous Rolling	Scale 0-10	ASTM D7684*		2		
Nonferrous Other	Scale 0-10	ASTM D7684*				
FILTER CONTAM	INANTS	method	limit/base	current	history1	history2
Sand/Dirt	Scale 0-10	ASTM D7684*		2		
Fibres	Scale 0-10	ASTM D7684*		1		
Spheres	Scale 0-10	ASTM D7684*				
Other	Scale 0-10	ASTM D7684*				
Patch Weight	mg	ASTM D7684*		35		
SAMPLE IMAGES	;	method	limit/base	current	history1	history2
Color				no image	no image	no image
Bottom				no image	no image	no image




FILTER REPORT

Machine Id LAND ROVER 24090 Component Filter

Fluid
{not provided} (--- GAL)





WEAR

The filter contained a light concentration of ferrous sliding wear particles. All other component wear rates are normal.