


OIL ANALYSIS REPORT

Sample Rating Trend



Machine Id

1610 DERSAN STREET

Diesel Engine

PETRO CANADA XR 4 SAE 15W40 (--- LTR)

DIAGNOSIS

Recommendation

No corrective action is recommended at this time. Resample at the next service interval to monitor. Please specify the component make and model with your next sample.

All component wear rates are normal.

Contamination

Light fuel dilution occurring. No other contaminants were detected in the oil.


Fluid Condition

The condition of the oil is acceptable for the time in service.

()			Jun 2023	May2024		
SAMPLE INFORM	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		WC0940153	WC0810822	
Sample Date		Client Info		23 May 2024	06 Jun 2023	
Machine Age	hrs	Client Info		0	0	
Oil Age	hrs	Client Info		0	0	
Oil Changed		Client Info		N/A	N/A	
Sample Status				MARGINAL	ATTENTION	
CONTAMINATION	١	method	limit/base	current	history1	history2
Water		WC Method	>0.2	NEG	NEG	
Glycol		WC Method		NEG	NEG	
WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185(m)	>100	2	2	
Chromium	ppm	ASTM D5185(m)	>20	0	0	
Nickel	ppm	ASTM D5185(m)	>4	0	0	
Titanium	ppm	ASTM D5185(m)		<1	8	
Silver	ppm	ASTM D5185(m)	>3	<1	0	
Aluminum	ppm	ASTM D5185(m)	>20	<1	2	
Lead	ppm	ASTM D5185(m)	>40	<1	<1	
Copper	ppm	ASTM D5185(m)	>330	<1	2	
Tin	ppm	ASTM D5185(m)	>15	0	0	
Antimony	ppm	ASTM D5185(m)		0	<1	
Vanadium	ppm	ASTM D5185(m)		0	<1	
Beryllium	ppm	ASTM D5185(m)		0	0	
Cadmium	ppm	ASTM D5185(m)		0	0	
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185(m)	1	27	410	
Barium	ppm	ASTM D5185(m)	1	0	0	
Molybdenum	ppm	ASTM D5185(m)	1	60	74	
Manganese	ppm	ASTM D5185(m)		0	<1	
Magnesium	ppm	ASTM D5185(m)	10	919	419	
Calcium	ppm	ASTM D5185(m)	3032	1078	1490	
Phosphorus	ppm	ASTM D5185(m)	1054	998	1087	
Zinc	ppm	ASTM D5185(m)	1332	1172	1138	
Sulfur	ppm	ASTM D5185(m)	3985	2767	2879	
Lithium	ppm	ASTM D5185(m)		<1	<1	
CONTAMINANTS		method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185(m)	>25	11	4	
Sodium	ppm	ASTM D5185(m)		1	2	
Potassium	ppm	ASTM D5185(m)	>20	<1	1	
Fuel	%	ASTM D7593*	>5	<u>^</u> 2.2	<u>▲</u> 2.5	
INFRA-RED		method	limit/base	current	history1	history2
Soot %	%	ASTM D7844*	>3	0	0	
Nitration	Abs/cm	ASTM D7624*	>20	5.3	5.2	
Sulfation	Abs/.1mm	ASTM D7415*	>30	18.7	21.4	



OIL ANALYSIS REPORT





CALA ISO 17025:2017 Accredited Laboratory

Laboratory Sample No.

: WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9 : WC0940153

Lab Number : 02643154 Unique Number : 5800693

Received **Tested**

: 20 Jun 2024

: 21 Jun 2024

: 21 Jun 2024 - Wes Davis

Diagnosed Test Package : MOB 1 (Additional Tests: FuelDilution, PercentFuel)

To discuss this sample report, contact Customer Service at 1-800-268-2131. Test denoted (*) outside scope of accreditation, (m) method modified, (e) tested at external lab. Validity of results and interpretation are based on the sample and information as supplied.

NORTHERN GENERATOR CO. LTD.

80 ASHBRIDGE CIRCLE,, UNIT #1 & 2 WOODBRIDGE, ON

CA L4L 3R5 Contact: Selome Afework selome@northerngenerator.com

T: (905)264-9744 F: (905)264-9714

Contact/Location: Selome Afework - NORWOO