

## **OIL ANALYSIS REPORT**

Sample Rating Trend

CONTAMINANT

Machine Id

# 333 MARKET DRIVE GEN #3

Component

Diesel Engine

Fluid {not provided} (--- GAL)

### DIAGNOSIS

#### Recommendation

NOTE: The bottle submitted did not contain sample for testing.

SAMPLE INFORM	IATION	method	limit/base	current	history1	history2
Sample Number		Client Info		wc	WC0795008	
Sample Date		Client Info		19 Mar 2024	21 Mar 2023	
Machine Age	hrs	Client Info		0	0	
Oil Age	hrs	Client Info		0	0	
Oil Changed		Client Info		N/A	N/A	
Sample Status				ABNORMAL	NORMAL	
CONTAMINATION		method	limit/base	current	history1	history2
Fuel		WC Method	>5	<1.0	0.8	
Water		WC Method	>0.2	NEG	NEG	
Glycol		WC Method		NEG	NEG	
VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	Visual*	NONE	NONE		
Yellow Metal	scalar	Visual*	NONE	NONE		
Precipitate	scalar	Visual*	NONE	NONE		
Silt	scalar	Visual*	NONE	NONE		
Debris	scalar	Visual*	NONE	NONE		
Sand/Dirt	scalar	Visual*	NONE	NONE		
Appearance	scalar	Visual*	NORML	▲ NOOIL		
Odor	scalar	Visual*	NORML	NORML	NORML	



### **OIL ANALYSIS REPORT**

**GRAPHS** 



CALA ISO 17025:2017 Accredited Laboratory

Laboratory Sample No. : WC Lab Number : 02643306 Unique Number : 5800845

Test Package : TEST

To discuss this sample report, contact Customer Service at 1-800-268-2131.

: WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9 NORTHERN GENERATOR CO. LTD. Received : 20 Jun 2024 Tested : 21 Jun 2024 Diagnosed

80 ASHBRIDGE CIRCLE,, UNIT #1 & 2 WOODBRIDGE, ON : 21 Jun 2024 - Kevin Marson CA L4L 3R5

Contact: Selome Afework selome@northerngenerator.com T: (905)264-9744

Test denoted (\*) outside scope of accreditation, (m) method modified, (e) tested at external lab. Validity of results and interpretation are based on the sample and information as supplied.

Contact/Location: Selome Afework - NORWOO

F: (905)264-9714