




# OIL ANALYSIS REPORT

Sample Rating Trend



## CONTAMINANT



Machine Id

## 1185 CALEDONIA

Component

Diesel Engine

Fluid

MOBIL DELVAC 1300 SUPER15W40 (--- LTR)

### DIAGNOSIS

#### ▲ Recommendation

NOTE: The bottle submitted did not contain sample for testing.

### SAMPLE INFORMATION

|               | method      | limit/base  | current            | history1    | history2 |
|---------------|-------------|-------------|--------------------|-------------|----------|
| Sample Number | Client Info |             | <b>WC0884759</b>   | WC0313569   | ---      |
| Sample Date   | Client Info |             | <b>22 Jan 2024</b> | 10 Jul 2019 | ---      |
| Machine Age   | hrs         | Client Info | <b>0</b>           | 0           | ---      |
| Oil Age       | hrs         | Client Info | <b>0</b>           | 0           | ---      |
| Oil Changed   | Client Info |             | <b>N/A</b>         | Changed     | ---      |
| Sample Status |             |             | <b>ABNORMAL</b>    | SEVERE      | ---      |

### CONTAMINATION

|       | method    | limit/base | current        | history1 | history2 |
|-------|-----------|------------|----------------|----------|----------|
| Fuel  | WC Method | >5         | <b>&lt;1.0</b> | 0.2      | ---      |
| Water | WC Method | >0.2       | <b>NEG</b>     | NEG      | ---      |

### CONTAMINANTS


|        | method | limit/base  | current    | history1 | history2 |
|--------|--------|-------------|------------|----------|----------|
| Glycol | %      | ASTM D7922* | <b>NEG</b> | ▲ 0.10   | ---      |

### VISUAL

|              | method | limit/base | current | history1       | history2 |
|--------------|--------|------------|---------|----------------|----------|
| White Metal  | scalar | Visual*    | NONE    | <b>NONE</b>    | VLITE    |
| Yellow Metal | scalar | Visual*    | NONE    | <b>NONE</b>    | NONE     |
| Precipitate  | scalar | Visual*    | NONE    | <b>NONE</b>    | NONE     |
| Silt         | scalar | Visual*    | NONE    | <b>NONE</b>    | NONE     |
| Debris       | scalar | Visual*    | NONE    | <b>NONE</b>    | VLITE    |
| Sand/Dirt    | scalar | Visual*    | NONE    | <b>NONE</b>    | NONE     |
| Appearance   | scalar | Visual*    | NORML   | ▲ <b>NOOIL</b> | NORML    |
| Odor         | scalar | Visual*    | NORML   | <b>NORML</b>   | NORML    |



# OIL ANALYSIS REPORT



## GRAPHS



**Laboratory** : WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9  
**Sample No.** : WC0884759  
**Lab Number** : 02643309  
**Unique Number** : 5800848  
**Test Package** : TEST

**NORTHERN GENERATOR CO. LTD.**  
 80 ASHBRIDGE CIRCLE,, UNIT #1 & 2  
 WOODBRIDGE, ON  
 CA L4L 3R5

Contact: Selome Afework  
 selome@northerngenerator.com

T: (905)264-9744  
 F: (905)264-9714

To discuss this sample report, contact Customer Service at 1-800-268-2131.  
 Test denoted (\*) outside scope of accreditation, (m) method modified, (e) tested at external lab.  
 Validity of results and interpretation are based on the sample and information as supplied.