

FILTER DEBRIS ANALYSIS

Sample Rating Trend



Machine Id

NISSAN 24108-B

Component Filter Fluid {not provided} (--- GAL)

DIAGNOSIS

Recommendation

We understand that this sample is for

warranty/insurance purposes. Diagnostician's Note: The majority of filter material was burnt filter paper consistent with a vehicle fire. The other material in the filter (wear particles, dirt) was not out of the ordinary for a normal oil service interval.

Wear Particles

The filter contained no appreciable wear particles. All filter wear levels are normal.

Contaminants

The filter contained only normal levels of contaminants, and debris. All filter contaminant levels are normal.

SAMPLE INFORM	IATION	method	limit/base	current	history1	history2
Sample Number		Client Info		WC0959462		
Sample Date		Client Info		20 Jun 2024		
Machine Age	hrs	Client Info		0		
Oil Age	hrs	Client Info		0		
Oil Changed		Client Info		N/A		
Sample Status				NORMAL		
CONTAMINATION	J	method	limit/base	current	history1	history2
Water		WC Method		NEG		
FILTER WEAR PAP	RTICLES	method	limit/base	current	history1	history2
Ferrous Rubbing	Scale 0-10	ASTM D7684*		2		
Ferrous Sliding	Scale 0-10	ASTM D7684*				
Ferrous Cutting	Scale 0-10	ASTM D7684*				
Ferrous Rolling	Scale 0-10	ASTM D7684*		2		
Ferrous Break-in	Scale 0-10	ASTM D7684*				
Ferrous Spheres	Scale 0-10	ASTM D7684*				
Ferrous Black Oxides	Scale 0-10	ASTM D7684*				
Ferrous Red Oxides	Scale 0-10	ASTM D7684*				
Ferrous Corrosive	Scale 0-10	ASTM D7684*				
Ferrous Other	Scale 0-10	ASTM D7684*				
Nonferrous Rubbing	Scale 0-10	ASTM D7684*		2		
Nonferrous Sliding	Scale 0-10	ASTM D7684*				
Nonferrous Cutting	Scale 0-10	ASTM D7684*				
Nonferrous Rolling	Scale 0-10	ASTM D7684*		2		
Nonferrous Other	Scale 0-10	ASTM D7684*				
FILTER CONTAM	INANTS	method	limit/base	current	history1	history2
Sand/Dirt	Scale 0-10	ASTM D7684*		2		
Fibres	Scale 0-10	ASTM D7684*				
Spheres	Scale 0-10	ASTM D7684*				
Other	Scale 0-10	ASTM D7684*		4		
Patch Weight	mg	ASTM D7684*		293		
SAMPLE IMAGES	;	method	limit/base	current	history1	history2
Color				no image	no image	no image
Bottom				no image	no image	no image



FILTER REPORT

Machine Id **NISSAN 24108-B** Component Filter Fluid {not provided} (--- GAL)



Magn: 60x Illum: RW



WEAR

The filter contained no appreciable wear particles. All filter wear levels are normal.