

OIL ANALYSIS REPORT

Sample Rating Trend



Machine Id **10 MILL** Component **Discharge Trunnion Bearing** Fluid SHELL OMALA S2 GX 320 (--- GAL)

DIAGNOSIS

Recommendation

Resample at the next service interval to monitor. NOTE: Please provide information regarding reservoir capacity, filter type and micron rating with next sample.

Wear

All component wear rates are normal.

Contamination

There is no indication of any contamination in the oil.

Fluid Condition

The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.

SAMPLE INFORM	1ATION	method	limit/base	current	history1	history2
Sample Number		Client Info		WC0898804		
Sample Date		Client Info		24 Jun 2024		
Machine Age	hrs	Client Info		0		
Oil Age	hrs	Client Info		0		
Oil Changed		Client Info		Not Changd		
Sample Status				NORMAL		
CONTAMINATION	١	method	limit/base	current	history1	history2
Water		WC Method	>2	NEG		
WEAR METALS		method	limit/base	current	history1	history2
PQ		ASTM D8184*		0		
Iron	ppm	ASTM D5185(m)	>20	14		
Chromium	ppm	ASTM D5185(m)	>20	0		
Nickel	ppm	ASTM D5185(m)	>20	<1		
Titanium	ppm	ASTM D5185(m)		0		
Silver	ppm	ASTM D5185(m)		0		
Aluminum	ppm	ASTM D5185(m)	>20	<1		
Lead	ppm	ASTM D5185(m)		3		
Copper	ppm	ASTM D5185(m)	>20	<1		
Tin	ppm	ASTM D5185(m)	>20	1		
Antimony	ppm	ASTM D5185(m)		1		
Vanadium	ppm	ASTM D5185(m)		0		
Beryllium	ppm	ASTM D5185(m)		0		
Cadmium	ppm	ASTM D5185(m)		0		
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185(m)	6.2	<1		
Barium	ppm	ASTM D5185(m)	0.0	0		
Molybdenum	ppm	ASTM D5185(m)	0	0		
Manganese	ppm	ASTM D5185(m)		<1		
Magnesium	ppm	ASTM D5185(m)	0	<1		
Calcium	ppm	ASTM D5185(m)	0.0	6		
Phosphorus	ppm	ASTM D5185(m)	290	249		
Zinc	ppm	ASTM D5185(m)	3.8	19		
Sulfur	ppm	ASTM D5185(m)	8167	7981		
Lithium	ppm	ASTM D5185(m)		<1		
CONTAMINANTS		method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185(m)	>15	0		
Sodium	ppm	ASTM D5185(m)		<1		
Potassium	ppm	ASTM D5185(m)	>20	0		
FLUID DEGRADA	TION	method	limit/base	current	history1	history2
Acid Number (AN)	mg KOH/g	ASTM D974*		0.44		



OIL ANALYSIS REPORT

White Melal a scalar Visual" NONE NONE Precipitale scalar Visual" NONE NONE Precipitale scalar Visual" NONE NONE Precipitale scalar Visual" NONE	Acid Number		VISUAL		method	limit/base	current	history1	history2
Sand/Dirit Bockar Weisalt NONE NONE	40		White Metal	scalar	Visual*	NONE	NONE		
Sand/Dirit Bockar Weisalt NONE NONE			Yellow Metal	scalar	Visual*	NONE	NONE		
Sand/Dirit Bockar Weisalt NONE NONE	30 -		Precipitate	scalar		NONE	NONE		
Sand/Dirit Bockar Weisalt NONE NONE	20 -			scalar	Visual*		NONE		
Sand/Dirit Bockar Weisalt NONE NONE	10+		Debris		Visual*	NONE			
Appearance scalar Visual* NORML NORML Wicksity 19:40°C			Sand/Dirt		Visual*	NONE	NONE		
Viscosity @ 40°C Free Water isolater Visual* -2 NEG		4/24							
Vecosity @ 40°C Proc Water is calar Visual >2 NEG Free Water is calar Visual >2 NEG Free Water is calar Visual >2 NEG Free Water is calar Visual >2 NEG NEG NEG NEG Neg State of the second visual >2 NEG Neg State of the second visual >2 Neg State of the second visual >2 Neg Neg State of the second visual >2 Neg State of the second visual >2 Neg	Jun 24	Jun2 ⁴							
Free Water is calar Visual NEG FLUID PROPERTIES method limitbase ourrent history1 history1 Visc @ 40°C c5t A5110723(r) 320 318 SAMPLE IMAGES notice C imitbase ourrent history1 history1 Notice @ 40°C c5t A5110723(r) 320 318 Color on image no image no image no image no image no image no image no image no image no image no image no image no image no image no image regiment of the second of t						>2			
Image: Description of the second s	60 -								
Image: Color Image: Color <td< td=""><td>50 - Abnormal</td><td></td><td></td><td></td><td></td><td>limit/base</td><td></td><td>history1</td><td>history</td></td<>	50 - Abnormal					limit/base		history1	history
SAMPLE IMAGES method initibase current history1 history1 Color no image no image no image no image no image no image no image no image no image Non-ferrous Metals uistoryt @ 40°C Non-ferrous Metals Non-ferrous Metals									
Image: Color Image: Color Image: Color Image: Color Image: Color Image: Color	20 - Gase 10 -								
Color in o image no image no image no image no image no image no image no image no image Non-ferrous Metals no no no no no no no no no no	00		SAMPLE IMAGE	5	method	limit/base	current	nistory i	nistoryz
PQ GRAPHS Ferrous Alloys GRAPHS Ferrous Alloys GRAPHS Ferrous Alloys GRAPHS Ferrous Alloys GRAPHS Ferrous Alloys GRAPHS Ferrous Metals Mon-ferrous Metals	Abnormal	24	Color				CIBBBBB DIV	no imago	no imago
Bottom no image no image no image Image no image no image no image Image Image no image no image Image Image Image no image no image Image Image Image Image no image no image Image Image Image Image Image Image Image Image Image Image Image Image Image Image Image Image Image Image Image Image Image Image Image	Jun24/2	Jun24/2	Color					noimage	no image
Bottom no image n									
Image: Comparison of the second se	Smore		Bottom					no image	no image
Image: Construction of the second	50 -								
Subjective Laboratory ::WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9 Wiscosity ::WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9 Viscosity :WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9 Wiscosity ::WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9 :WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9 Viscosity Wiscosity ::WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9 :WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9 Viscosity Wiscosity ::WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9 :WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9 Viscosity ::Wiscosity ::WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9 :WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9 :WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9 ::Wiscosity ::WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9 :Wiscosity :WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9 ::Wiscosity ::Wiscosity ::Wiscosity :WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9 :Wiscosity ::Wiscosity ::Wiscosity ::Wiscosity ::Wiscosity :Wiscosity :Wiscosity ::Wiscosity ::Wiscosity ::Wiscosity ::Wiscosity :Wiscosity :Wiscosit	00 Abnormal	_							
Image: state of the state state of the state of the state of the state of the	50					220			
Image: Second	50						Smare		
Won-ferrous Metals Image: Construct of the start o	54	V C	10 * names nickel			200	- 0		
Won-ferrous Metals Image: Construct of the start o	un24//	/ 1/	udd			180			
Non-ferrous Metals Image: Construction of the second s	7	-	5+			160			
Non-ferrous Metals Image: Construction of the second s						140			
Non-ferrous Metals Image: Second			24/24			120			
Non-ferrous Metals Image: Control of the second			Junt				Abnormal		
Viscosity @ 40°C Viscosity @ 40°C Opened Opened <			Non-ferrous Meta	als		100			
Viscosity @ 40°C Viscosity @						80			
Viscosity @ 40°C Viscosity @			o announce lead			60			
Viscosity @ 40°C Uscosity @ 40°			E 6 The second s			40			
Wiscosity @ 40°C Acid Number Viscosity @ 40°C Acid Number Mark Stress Sample No. Sources Sample No. Viscosity E Sources Number Viscosity E Sources Number Viscosity E Sources Sample No. Suboratory T est Package Number Viscosity E Sources Number Viscosity E Sources Sample No. Suboratory T est Package Number Viscosity E Sources Sample No. Suboratory T est Package Number Viscosity E Sources Sample No. Suboratory T est Package Number Viscosity E Sources Number V			4						
Viscosity @ 40°C			2			20	•		
Viscosity @ 40°C			1/24			0	54		
Viscosity @ 40°C			Jun24			Jun24	in24/2		
Image: State of the state						,			
Image: Source of the sector						-0.50	Acid Number		
Image: Solution of the second of the seco			T			B 0.40			
300 400 200 400 200 400 200 400 200 400 200 400 200 400 200 400 200 400 200 400 200 400 200 400 200 400 200 400 200 400 200 400 200 400 200 400 200 200 200 200 200 200 200 200 200 200 200 200 200 200 200 200 200 200 200 200 200 200 200 200 200 200 200 200 200 200 200 200 200 200 200 2						Ĕ 0.30			
300 400 200 400 200 400 200 400 200 400 200 400 200 400 200 400 200 400 200 400 200 400 200 400 200 400 200 400 200 400 200 400 200 400 200 400 200 200 200 200 200 200 200 200 200 200 200 200 200 200 200 200 200 200 200 200 200 200 200 200 200 200 200 200 200 200 200 200 200 200 200 2			王 320 - 9			- e 0.20			
Image: Solution of the second seco							1		
Vale - Clarabelle I Sample No. : WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9 Vale - Clarabelle I Sample No. : WC0898804 Lab Number : 02645008 Lab Number : 02645008 Laboratory : 5802547 Diagnosed : 04 Jul 2024 COPPER CLIFF, 0 Contact: Guy Gauth To discuss this sample report, contact Customer Service at 1-800-268-2131. Test denoted (*) outside scope of accreditation, (m) method modified, (e) tested at external lab.			280 Abnormal			0.00	1		
Vale - Clarabelle I Sample No. : WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9 Vale - Clarabelle I Sample No. : WC0898804 Lab Number : 02645008 Lab Number : 02645008 Laboratory : 5802547 Diagnosed : 04 Jul 2024 COPPER CLIFF, 0 Contact: Guy Gauth To discuss this sample report, contact Customer Service at 1-800-268-2131. Test denoted (*) outside scope of accreditation, (m) method modified, (e) tested at external lab.			24/24			24/24	24/24		
Sample No. : WC0898804 Received : 02 Jul 2024 MTW (Mill, Tailings&Wath Iso 17025:2017 Lab Number : 02645008 Tested : 04 Jul 2024 COPPER CLIFF, 0 Accredited Laboratory Unique Number : 5802547 Diagnosed <td: -="" 04="" 2024="" jul="" kevin="" marson<="" td=""> CA P0M 1 To discuss this sample report, contact Customer Service at 1-800-268-2131. Test denoted (*) outside scope of accreditation, (m) method modified, (e) tested at external lab. T: (705)682-56</td:>			lun			Junc	Jun		
Sample No. : WC0898804 Received : 02 Jul 2024 MTW (Mill, Tailings&Wath iso 17025:2017 Lab Number : 02645008 Tested : 04 Jul 2024 COPPER CLIFF, 0 Accredited Laboratory Unique Number : 5802547 Diagnosed <td: -="" 04="" 2024="" jul="" kevin="" marson<="" td=""> CA P0M 1 To discuss this sample report, contact Customer Service at 1-800-268-2131. Test denoted (*) outside scope of accreditation, (m) method modified, (e) tested at external lab. T: (705)682-56</td:>									
Iso 17025:2017 Lab Number : 02645008 Tested : 04 Jul 2024 COPPER CLIFF, 0 Accredited Laboratory Unique Number : 5802547 Diagnosed : 04 Jul 2024 - Kevin Marson CA P0M 1 To discuss this sample report, contact Customer Service at 1-800-268-2131. Test denoted (*) outside scope of accreditation, (m) method modified, (e) tested at external lab. T: (705)682-56							. 5H9		
Accredited Laboratory Unique Number : 5802547 Diagnosed <th: -="" 04="" 2024="" jul="" kevin="" marson<="" th=""> CA P0M 1 Contact: Guy Gauth Test Package : IND 2 Contact: Guy Gauth Contact: Guy Gauth To discuss this sample report, contact Customer Service at 1-800-268-2131. guy.gauthier@vale.c T: (705)682-568 Test denoted (*) outside scope of accreditation, (m) method modified, (e) tested at external lab. T: (705)682-568</th:>		Lab Manaka an							
LaboratoryTest Package : IND 2Contact: Guy GauthTo discuss this sample report, contact Customer Service at 1-800-268-2131.guy.gauthier@vale.cTest denoted (*) outside scope of accreditation, (m) method modified, (e) tested at external lab.T: (705)682-56	Accredited	•					n Marson	00.1	CA POM 1
Test denoted (*) outside scope of accreditation, (m) method modified, (e) tested at external lab. T: (705)682-56		Test Package	: IND 2	-				Contact	
		this sample report,	contact Customer Ser						
	-								

Report Id: INCOCLARA [WCAMIS] 02645008 (Generated: 07/04/2024 11:35:06) Rev: 1

Contact/Location: Guy Gauthier - INCOCLARA