

# **OIL ANALYSIS REPORT**

Sample Number

hrs

hrs

Sample Date

Machine Age

Oil Changed

Sample Status

Particles >21µm

Particles >38µm

Particles >71µm

**Oil Cleanliness** 

Oil Age

...

### NORMAL

## SAB1 SAB1 G3 Governor Hydraulic System ESSO TERESSO ISO 46 (1600 LTR)

#### DIAGNOSIS

Area

#### Recommendation

Resample at the next service interval to monitor. Please contact your representative for information regarding the proper sampling kits for your service. NOTE: We recommend using IND 3 test kits, this testkit includes Analytical Ferrography which provides a detailed morphological analysis of wear particles present in the fluid.

#### Wear

Component wear rates appear to be normal (unconfirmed).

#### Contamination

The system cleanliness is acceptable for your target ISO 4406 cleanliness code. The system and fluid cleanliness is acceptable.

#### Fluid Condition

The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.

Nov2013	Jan2015 Oct2016	Feb2018 Nov2019 Aut	2021 Mar2023	
			<u></u>	
			ti i i ti i i i	
			1110101010101010	
			terreret rearran	
			20100100200200000	

#### SAMPLE INFORMATION method WC0933965 WC0642866 WC0864653 **Client Info** 15 May 2024 21 Dec 2023 03 Jul 2024 Client Info **Client Info** 0 0 0 Client Info 0 0 0 **Client Info** N/A N/A N/A NORMAL NORMAL NORMAL

CONTAMINATION		method	limit/base	current	history1	history2
Water		WC Method	>0.05	NEG	NEG	NEG
WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185(m)	>20	<1	<1	<1
Chromium	ppm	ASTM D5185(m)	>20	0	0	0
Nickel	ppm	ASTM D5185(m)	>20	<1	0	0
Titanium	ppm	ASTM D5185(m)		0	0	0
Silver	ppm	ASTM D5185(m)		0	0	0
Aluminum	ppm	ASTM D5185(m)	>20	<1	0	<1
Lead	ppm	ASTM D5185(m)	>20	0	0	0
Copper	ppm	ASTM D5185(m)	>20	<1	<1	<1
Tin	ppm	ASTM D5185(m)	>20	0	0	0
Antimony	ppm	ASTM D5185(m)		0	0	0
Vanadium	ppm	ASTM D5185(m)		0	0	0
Beryllium	ppm	ASTM D5185(m)		0	0	0
Cadmium	ppm	ASTM D5185(m)		0	0	0
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185(m)	0	<1	0	0
Barium	ppm	ASTM D5185(m)		0	0	0
Molybdenum	ppm	ASTM D5185(m)	0	0	0	0
Manganese	ppm	ASTM D5185(m)		0	0	0
Magnesium	ppm	ASTM D5185(m)	0	0	0	0
Calcium	ppm	ASTM D5185(m)	0	<1	0	<1
Phosphorus	ppm	ASTM D5185(m)	2.4	8	1	1
Zinc	ppm	ASTM D5185(m)	0	1	<1	1
Sulfur	ppm	ASTM D5185(m)		719	742	818
Lithium	ppm	ASTM D5185(m)		<1	<1	<1
CONTAMINANTS	5	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185(m)	>15	0	0	<1
Sodium	ppm	ASTM D5185(m)		0	0	0
Potassium	ppm	ASTM D5185(m)	>20	<1	<1	<1
FLUID CLEANLIN	IESS	method	limit/base	current	history1	history2
Particles >4µm		ASTM D7647	>2500	182	168	862
Particles >6µm		ASTM D7647	>640	64	54	201
Particles >14µm		ASTM D7647	>80	6	7	8

>20

>4

ISO 4406 (c) >18/16/13

ASTM D7647

ASTM D7647

ASTM D7647 >3

1

0

0

15/13/10

2

0

0

3


0


0


15/13/10




# **OIL ANALYSIS REPORT**










FLUID DEGRADA	TION	method	limit/base	current	history1	history2
Acid Number (AN)	mg KOH/g	ASTM D974*	0.02	0.10	0.08	0.11
VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	Visual*	NONE	NONE	NONE	NONE
Yellow Metal	scalar	Visual*	NONE	NONE	NONE	NONE
Precipitate	scalar	Visual*	NONE	NONE	NONE	NONE
Silt	scalar	Visual*	NONE	NONE	NONE	NONE
Debris	scalar	Visual*	NONE	NONE	NONE	NONE
Sand/Dirt	scalar	Visual*	NONE	NONE	NONE	NONE
Appearance	scalar	Visual*	NORML	NORML	NORML	NORML
Odor	scalar	Visual*	NORML	NORML	NORML	NORML
Emulsified Water	scalar	Visual*	>0.05	NEG	NEG	NEG
Free Water	scalar	Visual*		NEG	NEG	NEG
FLUID PROPERT	IES	method	limit/base	current	history1	history2
Visc @ 40°C	cSt	ASTM D7279(m)	46	45.4	45.4	45.4
SAMPLE IMAGES	5	method	limit/base	current	history1	history2

Color



Bottom



Laboratory : WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9 CALA Sample No. : WC0933965 Received : 04 Jul 2024 Lab Number : 02645453 Tested : 05 Jul 2024 ISO 17025:2017 Accredited Laboratory Unique Number : 5802992 Diagnosed : 05 Jul 2024 - Kevin Marson Test Package : IND 2 (Additional Tests: TAN Man) To discuss this sample report, contact Customer Service at 1-800-268-2131. Test denoted (\*) outside scope of accreditation, (m) method modified, (e) tested at external lab. Validity of results and interpretation are based on the sample and information as supplied.

**Ontario Power Generation** 

NIAGARA PLANT GROUP,, 14000 NIAGARA PKWY NIAGARA ON THE LAKE, ON n CA LOS 1J0 Contact: Michael Brochu mike.brochu@opg.com T: (905)357-0322 F: (905)374-5466

Report Id: ONTQUE [WCAMIS] 02645453 (Generated: 07/05/2024 09:39:41) Rev: 1

```
Submitted By: ?
Page 2 of 2
```