




OIL ANALYSIS REPORT

Sample Rating Trend



NORMAL



Machine Id

CMP 2

Component

Tank Hydraulic System

Fluid

PETRO CANADA ATF D3M (--- GAL)

DIAGNOSIS

Recommendation

This is a baseline read-out on the submitted sample.

Contamination

ISO Cleanliness Code (ISO 4406:1999): 18/16/12;
Cumulative particle counts >4µm = 1528, >6µm = 358, >14µm = 30, >21µm = 8, >38µm = 1, >71µm = 0.

SAMPLE INFORMATION

	method	limit/base	current	history1	history2
Sample Number	Client Info		WC0962539	---	---
Sample Date	Client Info		08 Jul 2024	---	---
Machine Age	hrs	Client Info	0	---	---
Oil Age	hrs	Client Info	0	---	---
Oil Changed	Client Info		N/A	---	---
Sample Status			NORMAL	---	---

CONTAMINATION

	method	limit/base	current	history1	history2
Water	WC Method	>0.05	NEG	---	---

FLUID CLEANLINESS

	method	limit/base	current	history1	history2
Particles >4µm	ASTM D7647	>40000	1528	---	---
Particles >6µm	ASTM D7647	>2500	358	---	---
Particles >14µm	ASTM D7647	>80	30	---	---
Particles >21µm	ASTM D7647	>20	8	---	---
Particles >38µm	ASTM D7647	>4	1	---	---
Particles >71µm	ASTM D7647	>3	0	---	---
Oil Cleanliness	ISO 4406 (c)	>22/18/13	18/16/12	---	---

VISUAL



	method	limit/base	current	history1	history2
White Metal	scalar	Visual*	NONE	VLITE	---
Yellow Metal	scalar	Visual*	NONE	NONE	---
Precipitate	scalar	Visual*	NONE	NONE	---
Silt	scalar	Visual*	NONE	NONE	---
Debris	scalar	Visual*	NONE	NONE	---
Sand/Dirt	scalar	Visual*	NONE	NONE	---
Appearance	scalar	Visual*	NORML	NORML	---
Odor	scalar	Visual*	NORML	NORML	---

SAMPLE IMAGES


	method	limit/base	current	history1	history2
Color				<i>no image</i>	<i>no image</i>
Bottom				<i>no image</i>	<i>no image</i>



OIL ANALYSIS REPORT



GRAPHS



Laboratory : WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9
Sample No. : WC0962539
Lab Number : 02646822
Unique Number : 5812374
Test Package : TEST (Additional Tests: PrtCount)

Skyjack - Plant 2 (div of Linamar)
 201 Woodlawn Rd. W.
 Guelph, ON
 CA N1H 1B8
 Contact: Vishal Kanwar
 vishal.kanwar@skyjack.com

To discuss this sample report, contact Customer Service at 1-800-268-2131.
 Test denoted (*) outside scope of accreditation, (m) method modified, (e) tested at external lab.
 Validity of results and interpretation are based on the sample and information as supplied.

T:
 F: (519)837-4895