

OIL ANALYSIS REPORT

PUMPHOUSE/CASTER SPRAY WATER PUMPS C - Caster Spray Water Electric Pump IB

Lube System

PETRO CANADA HYDREX AW 100 (1 GAL)





DIAGNOSIS

Recommendation

We advise that you check all areas where dirt can enter the system. We recommend that you drain the oil from the component if this has not already been done. The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather. We recommend an early resample to monitor this condition.

Wear

Iron ppm levels are abnormal. A sharp increase in the iron level is noted. The low ferrous density (PQ) index indicates the wear metal levels are due to corrosion.

Contamination

There is a moderate concentration of dirt present in the oil. High amount of ingressed dirt has caused abrasive wear to the component.


Fluid Condition


The oil viscosity is lower than typical, possibly indicating the addition of lighter grade oil. The AN level is acceptable for this fluid. The oil is no longer serviceable as a result of the abnormal and/or severe wear.


SAMPLE INFORM	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		WC0968461	WC0898666	WC0850118
Sample Date		Client Info		17 Jul 2024	10 Jan 2024	16 Aug 2023
Machine Age	hrs	Client Info		0	0	0
Oil Age	hrs	Client Info		0	0	0
Oil Changed		Client Info		N/A	N/A	N/A
Sample Status				ABNORMAL	NORMAL	ABNORMAL
CONTAMINATIO	V	method	limit/base	current	history1	history2
Water		WC Method	>1	NEG	NEG	NEG
WEAR METALS		method	limit/base	current	history1	history2
PQ		ASTM D8184*	>DFLT	9	12	0
Iron	ppm	ASTM D5185(m)	>20	^ 72	23	29
Chromium	ppm	ASTM D5185(m)	>20	<1	0	<1
Nickel	ppm	ASTM D5185(m)	>20	1	0	<1
Titanium	ppm	ASTM D5185(m)		0	0	0
Silver	ppm	ASTM D5185(m)		0	0	<1
Aluminum	ppm	ASTM D5185(m)	>20	1	<1	<1
Lead	ppm	ASTM D5185(m)	>20	1	2	4
Copper	ppm	ASTM D5185(m)	>20	10	4	<u>^</u> 28
Tin	ppm	ASTM D5185(m)	>20	0	0	2
Antimony	ppm	ASTM D5185(m)		<1	0	0
Vanadium	ppm	ASTM D5185(m)		0	0	0
Beryllium	ppm	ASTM D5185(m)		0	0	0
Cadmium	ppm	ASTM D5185(m)		0	0	0
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185(m)	0	<1	0	<1
Barium	ppm	ASTM D5185(m)	0	0	0	0
Molybdenum	ppm	ASTM D5185(m)	0	0	0	0
Manganese	ppm	ASTM D5185(m)	0	<1	0	<1
Magnesium	ppm	ASTM D5185(m)	0	6	2	<1
Calcium	ppm	ASTM D5185(m)	50	33	38	48
Phosphorus	ppm	ASTM D5185(m)	330	440	426	344
Zinc	ppm	ASTM D5185(m)	430	319	349	396
Sulfur	ppm	ASTM D5185(m)	760	2526	2541	2454
Lithium	ppm	ASTM D5185(m)		2	<1	<1
CONTAMINANTS	3	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185(m)	>15	<u> </u>	14	3
Sodium	ppm	ASTM D5185(m)		<1	0	4
Potassium	ppm	ASTM D5185(m)	>20	<1	<1	<1





OIL ANALYSIS REPORT











FLUID CLEANLIN	ESS	method	limit/base	current	history1	history2
	LUU		IIIIII/Dase		,	•
Particles >4µm		ASTM D7647		835588	183587	118169
Particles >6µm		ASTM D7647		183067	84570	52474
Particles >14μm		ASTM D7647	>10240000	9132	3520	2374
Particles >21µm		ASTM D7647		1729	918	460
Particles >38μm		ASTM D7647	>640000	26	78	9
Particles >71μm		ASTM D7647		0	7	1
Oil Cleanliness		ISO 4406 (c)	>/30/30	27/25/20	25/24/19	24/23/18
FLUID DEGRADATION		method	limit/base	current	history1	history2
Acid Number (AN)	mg KOH/g	ASTM D974*	0.60	0.47	0.74	0.51
VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	Visual*	NONE	VLITE	NONE	NONE
Yellow Metal	scalar	Visual*	NONE	NONE	NONE	VLITE
Precipitate	scalar	Visual*	NONE	NONE	LIGHT	NONE
Silt	scalar	Visual*	NONE	NONE	NONE	NONE
Debris	scalar	Visual*	NONE	LIGHT	NONE	VLITE
Sand/Dirt	scalar	Visual*	NONE	NONE	NONE	NONE
Appearance	scalar	Visual*	NORML	NORML	NORML	NORML
Odor	scalar	Visual*	NORML	NORML	NORML	NORML
Emulsified Water	scalar	Visual*	>1	NEG	NEG	NEG
Free Water	scalar	Visual*		NEG	NEG	NEG
FLUID PROPERTI	IES	method	limit/base	current	history1	history2
Visc @ 40°C	cSt	ASTM D7279(m)	101	<u> </u>	123	94.1
SAMPLE IMAGES	1	method	limit/base	current	history1	history2
				4		00850118
Color						
Bottom						



CALA ISO 17025:2017 Accredited Laboratory

Laboratory Sample No.

Unique Number : 5814089

: WC0968461 Lab Number : 02648537

To discuss this sample report, contact Customer Service at 1-800-268-2131.

: WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9

Received : 17 Jul 2024 **Tested** : 19 Jul 2024 Diagnosed

: 19 Jul 2024 - Kevin Marson

STELCO - BOSC - Basic Oxygen Slab Caster 2330 Regional Road #3, Door: BOSC8 NANTICOKE, ON CA NOA 1L0

Contact: Tom Walden Thomas.Walden@stelco.com T: (519)587-4541

F: (519)587-7702

Test denoted (*) outside scope of accreditation, (m) method modified, (e) tested at external lab. Validity of results and interpretation are based on the sample and information as supplied.

Test Package : IND 2 (Additional Tests: Bottom, PQ, TAN Man)