


OIL ANALYSIS REPORT



KANSAS/44/EG - EXCAVATOR 20.24W [KANSAS^44^EG - EXCAVATOR]

Component
Swing Drive

MOBIL MOBILTRANS HD 50 (--- GAL)





Recommendation

Resample at the next service interval to monitor.

All component wear rates are normal.

Contamination

There is no indication of any contamination in the


Fluid Condition


The condition of the oil is acceptable for the time in service.


SAMPLE INFORM	IATION	method	limit/base	current	history1	history2
Sample Number		Client Info		WC0453797	WC0339482	WCCF1562
Sample Date		Client Info		16 Jul 2020	09 Aug 2019	22 Jun 2018
Machine Age	hrs	Client Info		5810	5281	4844
Oil Age	hrs	Client Info		0	0	0
Oil Changed		Client Info		Changed	N/A	N/A
Sample Status				NORMAL	NORMAL	NORMAL
CONTAMINATION	١	method	limit/base	current	history1	history2
Water		WC Method	>0.2	NEG	NEG	NEG
WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>400	31	26	69
Chromium	ppm	ASTM D5185m	>10	<1	<1	1
Nickel	ppm	ASTM D5185m		<1	<1	0
Titanium	ppm	ASTM D5185m		0	0	0
Silver	ppm	ASTM D5185m		0	0	0
Aluminum	ppm	ASTM D5185m	>25	1	2	<1
Lead	ppm	ASTM D5185m	>50	<1	0	0
Copper	ppm	ASTM D5185m		<1	<1	<1
Tin	ppm	ASTM D5185m	>10	0	0	0
Antimony	ppm	ASTM D5185m		0	0	0
Vanadium	ppm	ASTM D5185m		0	0	0
Cadmium	ppm	ASTM D5185m		0	0	0
ADDITIVES	PPIII	method	limit/base			history2
			iiiiii/base	current	history1	
Boron	ppm	ASTM D5185m		4	7	21
Barium	ppm	ASTM D5185m		0	<1	<1
Molybdenum	ppm	ASTM D5185m		2	2	14
Manganese	ppm	ASTM D5185m		<1	<1	2
Magnesium	ppm	ASTM D5185m		8	8	11
Calcium	ppm	ASTM D5185m		3068	2894	3074
Phosphorus	ppm	ASTM D5185m		969	978	855
Zinc	ppm	ASTM D5185m		1088	1121	1068
Sulfur	ppm	ASTM D5185m		15886	11917	7008
CONTAMINANTS		method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>50	7	7	8
Sodium	ppm	ASTM D5185m		2	1	4
Potassium	ppm	ASTM D5185m	>20	2	0	4
VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Yellow Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Precipitate	scalar	*Visual	NONE	NONE	NONE	NONE
Silt	scalar	*Visual	NONE	NONE	NONE	NONE
Debris	scalar	*Visual	NONE	NONE	NONE	NONE
Sand/Dirt	scalar	*Visual	NONE	NONE	NONE	NONE
Appearance	scalar	*Visual	NORML	NORML	NORML	NORML
Odor	scalar	*Visual	NORML	NORML	NORML	NORML
Emulsified Water	scalar	*Visual	>0.2	NEG	NEG nitted√₽yĠRICHA	NEG




OIL ANALYSIS REPORT













Certificate 12367

Sample No.

Lab Number : 05029331 Unique Number : 9114492

Test Package : MOBCE

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 : WC0453797

Received : 27 Jul 2020 **Tested** : 29 Jul 2020 Diagnosed : 29 Jul 2020 - Don Baldridge

SHERWOOD CONSTRUCTION CO INC 3219 WEST MAY ST

WICHITA, KS US 67213

Contact: DOUG KING doug.king@sherwood.net T: (316)617-3161

To discuss this sample report, contact Customer Service at 1-800-237-1369. * - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

F: x: