

# **OIL ANALYSIS REPORT**

Sample Rating Trend

## NORMAL

## MELT SHOP LADLE TURRETT - 2:30 Component

Lower Grease Fluid NOT GIVEN (--- QTS)

## Recommendation

Resample at the next service interval to monitor. Insufficient sample was received to conduct all the routine laboratory tests.

### Wear

{not applicable}

**Grease Condition** {not applicable}

Contaminants

{not applicable}


Jun2021										
SAMPLE INFORM	IATION	method	limit/base	current	history 1	history 2				
Sample Number		Client Info		WCI2295761						
Sample Date		Client Info		13 Jun 2021						
Machine Age	hrs	Client Info		0						
Grease Age	hrs	Client Info		0						
Grease Serviced		Client Info		N/A						
Sample Status				NORMAL						
VISUAL		method	limit/base	current	history 1	history 2				
VISUAL White Metal	scalar	method *Visual	limit/base	current	history 1	history 2				
	scalar scalar									
White Metal		*Visual	NONE	NONE						
White Metal Yellow Metal	scalar	*Visual *Visual	NONE NONE	NONE NONE						
White Metal Yellow Metal Precipitate	scalar scalar	*Visual *Visual *Visual	NONE NONE NONE	NONE NONE NONE						
White Metal Yellow Metal Precipitate Silt	scalar scalar scalar	*Visual *Visual *Visual *Visual	NONE NONE NONE	NONE NONE NONE NONE						
White Metal Yellow Metal Precipitate Silt Debris	scalar scalar scalar scalar	*Visual *Visual *Visual *Visual *Visual	NONE NONE NONE NONE	NONE NONE NONE NONE NONE						
White Metal Yellow Metal Precipitate Silt Debris Sand/Dirt	scalar scalar scalar scalar scalar	*Visual *Visual *Visual *Visual *Visual *Visual	NONE NONE NONE NONE NONE	NONE NONE NONE NONE NONE NONE	  					
White Metal Yellow Metal Precipitate Silt Debris Sand/Dirt Appearance	scalar scalar scalar scalar scalar scalar	*Visual *Visual *Visual *Visual *Visual *Visual	NONE NONE NONE NONE NONE NORML	NONE NONE NONE NONE NONE NONE	  	  				

SAMPLE IMAGES	method	limit/base	current	history 1	history 2
Color				no image	no image
Bottom				no image	no image



# **OIL ANALYSIS REPORT**





: WearCheck USA - 501 Madison Ave., Cary, NC 27513 **OUTOKUMPU STAINLESS USA** Laboratory Sample No. : WCI2295761 Received : 14 Jun 2021 HWY 43 N Lab Number : 05279114 Diagnosed : 25 Jun 2021 CALVERT, AL Unique Number : 9543047 Diagnostician : Doug Bogart US 36513 Test Package : IND 2 (Additional Tests: KF, PQ, PrtCount) Contact: MARIO JOHNSON Certificate L2367 To discuss this sample report, contact Customer Service at 1-800-237-1369. Mario.johnson@outokumpu.com \* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. T: (251)321-4105 Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012) F: x:

Contact/Location: MARIO JOHNSON - OUTCALAL

Page 2 of 2