




OIL ANALYSIS REPORT

Sample Rating Trend



FUEL



Machine Id
NETWORK LOGISTICS E10 R87

Component
Gasoline
Fluid
NOT GIVEN (--- GAL)

DIAGNOSIS

Recommendation

We advise that you check for the source of diesel fuel. Sample is almost 50% diesel fuel.

Contamination

There is a high amount of diesel fuel present in the gasoline.

Fluid Condition

The gasoline is no longer serviceable due to the presence of contaminants.



SAMPLE INFORMATION

	method	limit/base	current	history1	history2
Sample Number	Client Info		WC05637286	---	---
Sample Date	Client Info		08 Sep 2022	---	---
Machine Age	hrs	Client Info	0	---	---
Oil Age	hrs	Client Info	0	---	---
Oil Changed		Client Info	N/A	---	---
Sample Status			SEVERE	---	---

CONTAMINANTS

	method	limit/base	current	history1	history2
Fuel	%	ASTM D3524	45.0	---	---


SAMPLE IMAGES

	method	limit/base	current	history1	history2
Color				no image	no image
Bottom				no image	no image




OIL ANALYSIS REPORT

Fuel Dilution




GRAPHS

Ferrous Alloys



Non-ferrous Metals



Certificate L2367

Laboratory : WearCheck USA - 501 Madison Ave., Cary, NC 27513
Sample No. : WC05637286 **Received** : 08 Sep 2022
Lab Number : **05637286** **Diagnosed** : 14 Sep 2022
Unique Number : 10126816 **Diagnostician** : Doug Bogart
Test Package : TEST (Additional Tests: PercentFuel)

To discuss this sample report, contact Customer Service at 1-800-237-1369.

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

COUCH OIL COMPANY
 2907 HILLSBOROUGH RD
 DURHAM, NC
 US 27705

Contact: JESSE BROWN
 jesse@couchoilcompany.com

T: (919)285-5408

F: