


PROBLEM SUMMARY

Area HOTLINE/PUSHER FURNACES Machine Id UPENDER HYD @ PUSHER 1406-F01-0090 Component

Hydraulic System

BENZ OIL ULTRA GUARD 552 (--- GAL)

COMPONENT CONDITION SUMMARY



RECOMMENDATION

We recommend you service the filters on this component. Resample at the next service interval to monitor.

5x202

ISO

Sample Rating Trend

PROBLEMATIC TEST RESULTS									
Sample Status			ABNORMAL						
Particles >4µm	ASTM D7647	>5000	<u> </u>						
Particles >6µm	ASTM D7647	>1300	6 5531						
Particles >14µm	ASTM D7647	>160	<u> </u>						
Oil Cleanliness	ISO 4406 (c)	>19/17/14	A 22/20/15						

Customer Id: CONMUSAL Sample No.: KFS0001919 Lab Number: 05659609 Test Package: PLANT



To manage this report scan the QR code

To discuss the diagnosis or test data: Jonathan Hester +1 919-379-4092 x4092 <u>jhester@wearcheckusa.com</u>

To change component or sample information: Customer Service +1 1-800-237-1369 customerservice@wearcheck.com

RECOMMENDED ACTIONS						
Action	Status	Date	Done By	Description		
Change Filter	MISSED	Jan 24 2023	?	We recommend you service the filters on this component.		

HISTORICAL DIAGNOSIS



OIL ANALYSIS REPORT

Area HOTLINE/PUSHER FURNACES Machine Id UPENDER HYD @ PUSHER 1406-F01-0090 Component

Hydraulic System

BENZ OIL ULTRA GUARD 552 (--- GAL)

DIAGNOSIS

Recommendation

We recommend you service the filters on this component. Resample at the next service interval to monitor.

Wear

All component wear rates are normal.

Contamination

There is a high amount of particulates present in the oil.

Fluid Condition

The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.

						Λ
1406-F01-(1090					
				Sep2022		
SAMPLE INFORM		method	limit/base	current	history1	history2
		Client Info		KFS0001919		motoryz
Sample Number Sample Date		Client Info		27 Sep 2022		
Machine Age	hrs	Client Info		0		
Oil Age	hrs	Client Info		0		
Oil Changed	1110	Client Info		N/A		
Sample Status				ABNORMAL		
WEAR METALS		method	limit/base	current	history1	history2
	2222					
Iron	ppm	ASTM D5185m	>20	0		
Chromium Nickel	ppm		>20	<1		
Titanium	ppm	ASTM D5185m	>20	0 <1		
Silver	ppm	ASTM D5185m ASTM D5185m		<1 0		
Aluminum	ppm	ASTM D5185m ASTM D5185m	>20	0 <1		
Lead	ppm	ASTM D5185m	>20	<1		
	ppm	ASTM D5185m		<1		
Copper Tin	ppm	ASTM D5185m	>20	۰ ۱		
Vanadium	ppm	ASTM D5185m	>20	0		
Cadmium	ppm	ASTM D5185m		0		
	ppm					
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m		0		
Barium	ppm	ASTM D5185m		0		
Molybdenum	ppm	ASTM D5185m		<1		
Manganese	ppm	ASTM D5185m		0		
Magnesium	ppm	ASTM D5185m		0		
Calcium	ppm	ASTM D5185m		0		
Phosphorus	ppm	ASTM D5185m		328		
Zinc	ppm	ASTM D5185m		0		
Sulfur	ppm	ASTM D5185m		1083		
CONTAMINANTS	6	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>15	1		
Sodium	ppm	ASTM D5185m		0		
Potassium	ppm	ASTM D5185m	>20	0		
Water	%	ASTM D6304	>0.05	NEG		
FLUID CLEANLIN	NESS	method	limit/base	current	history1	history2
Particles >4µm		ASTM D7647	>5000	A 25269		
Particles >6µm		ASTM D7647	>1300	<u> </u>		
Particles >14µm		ASTM D7647	>160	<u> </u>		
Particles >21µm		ASTM D7647	>40	30		
Particles >38µm		ASTM D7647	>10	1		
Particles >71µm		ASTM D7647	>3	0		
Oil Cleanliness		ISO 4406 (c)	>19/17/14	A 22/20/15		
FLUID DEGRADA	ATION	method	limit/base	current	history1	history2
Acid Number (AN)	mg KOH/g	ASTM D8045		1.30		
. ,	- 0					

Sample Rating Trend

ISO



Acid Number

(B/HOX) B 0.8

Acid Number

0.2 0.0

58

57.

40°C)

3 56.9

56

55

Sep27/22

OIL ANALYSIS REPORT

method


limit/base


current


history1


history2

VISUAL









* - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

Viscosity @ 40°C

Laboratory

Sample No.

Lab Number

joel.even@constellium.com

T: (256)740-7490

Page 4 of 4

F: