

OIL ANALYSIS REPORT

Sample Rating Trend

NORMAL



CATERPILLAR 980M 6141 (S/N KRS00885) Component Front Differential

TULCO LUBSOIL TO-4 50 (3 GAL)

DIAGNOSIS

Recommendation

Resample at the next service interval to monitor.

Wear

All component wear rates are normal.

Contamination

There is no indication of any contamination in the oil.


Fluid Condition

The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.

SAMPLE INFORM	IATION	method	limit/base	current	history1	history2
Sample Number		Client Info		TO10001630		
Sample Date		Client Info		25 Oct 2022		
Machine Age	hrs	Client Info		9802		
Oil Age	hrs	Client Info		0		
Oil Changed		Client Info		Changed		
Sample Status				NORMAL		
CONTAMINATION	N	method	limit/base	current	history1	history2
Water		WC Method	>.2	NEG		
WEAR METALS		method	limit/base	current	history1	history2
PQ		ASTM D8184		17		
Iron	ppm	ASTM D5185m	>500	28		
Chromium	ppm	ASTM D5185m	>3	0		
Nickel	ppm	ASTM D5185m	>3	0		
Titanium	ppm	ASTM D5185m	>2	0		
Silver	ppm	ASTM D5185m	>2	0		
Aluminum	ppm	ASTM D5185m	>30	0		
Lead	ppm	ASTM D5185m	>13	0		
Copper	ppm	ASTM D5185m	>103	6		
Tin	ppm	ASTM D5185m	>5	0		
Vanadium	ppm	ASTM D5185m		0		
Cadmium	ppm	ASTM D5185m		0		
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m		16		
Barium	ppm	ASTM D5185m		0		
Molybdenum	ppm	ASTM D5185m		24		
Manganese	ppm	ASTM D5185m		1		
Magnesium	ppm	ASTM D5185m		98		
Calcium	ppm	ASTM D5185m		1595		
Phosphorus	ppm	ASTM D5185m		716		
Zinc	ppm	ASTM D5185m		894		
Sulfur	ppm	ASTM D5185m		3052		
CONTAMINANTS		method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>100	4		
Sodium	ppm	ASTM D5185m		0		
Potassium	ppm	ASTM D5185m	>20	0		
FLUID DEGRADA	TION	method	limit/base	current	history1	history2
Acid Number (AN)	mg KOH/g	ASTM D8045		1.75		



OIL ANALYSIS REPORT



To discuss this sample report, contact Customer Service at 1-800-237-1369.

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

ANCHOR STONE TULSA ROCK

Contact: MIKE SNYDER

no image

no image

no image

no image

Contact/Location: MIKE SNYDER - ANCTUL

TULSA, OK

US 74137