


OIL ANALYSIS REPORT

ЭТ







Machine Id VILTER
Component
New (Unused) Oil
Fluid
{not provided} (--- QTS)

DIAGNOSIS

Recommendation

This is a baseline sample for RULer.

SAMPLE INFORM	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		WC05749976		
Sample Date		Client Info		25 Jan 2023		
Machine Age	hrs	Client Info		0		
Oil Age	hrs	Client Info		0		
Oil Changed		Client Info		N/A		
Sample Status				NORMAL		
FLUID DEGRADA	TION	method	limit/base	current	history1	history2
MPC Varnish Potential	Scale	ASTM D7843	>15	1		
SAMPLE IMAGES	3	method	limit/base	current	history1	history2
Color				no image	no image	no image
Bottom				no image	no image	no image
MPC				734	no image	no image

