

# **OIL ANALYSIS REPORT**

RIG 1 R1-TD-HYD

Component **Hydraulic System** 

AW HYDRAULIC OIL ISO 32 (--- GAL)

# Sample Rating Trend



# **DIAGNOSIS**

## Recommendation

No corrective action is recommended at this time. Resample at the next service interval to monitor.

All component wear rates are normal.

# Contamination

There is a moderate amount of silt (particulates < 14 microns in size) present in the oil.


## **Fluid Condition**


The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.


		ec2019 Ap	r2020 Jan2021 Jul2	021 Mar2022 Jul2022 (	lct2022	
SAMPLE INFORM	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		KL0009728	KL0007975	KL0009796
Sample Date		Client Info		20 Jan 2023	21 Dec 2022	28 Oct 2022
Machine Age	days	Client Info		0	44911	44855
Oil Age	days	Client Info		0	0	0
Oil Changed		Client Info		N/A	N/A	N/A
Sample Status				ATTENTION	NORMAL	NORMAL
WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>20	2	0	2
Chromium	ppm	ASTM D5185m	>10	0	0	0
Nickel	ppm	ASTM D5185m	>10	0	0	0
Titanium	ppm	ASTM D5185m		0	0	0
Silver	ppm	ASTM D5185m		0	0	<1
Aluminum	ppm	ASTM D5185m	>10	0	0	0
Lead	ppm	ASTM D5185m	>10	0	0	0
Copper	ppm	ASTM D5185m	>75	<1	0	<1
Tin	ppm	ASTM D5185m	>10	0	0	0
Vanadium	ppm	ASTM D5185m		0	0	0
Cadmium	ppm	ASTM D5185m		0	0	0
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m	5	0	0	0
Barium	ppm	ASTM D5185m	5	<1	0	0
Molybdenum	ppm	ASTM D5185m	5	0	0	0
Manganese	ppm	ASTM D5185m		0	0	0
Magnesium	ppm	ASTM D5185m	25	2	0	1
Calcium	ppm	ASTM D5185m	200	43	36	46
Phosphorus	ppm	ASTM D5185m	300	326	334	333
Zinc	ppm	ASTM D5185m	370	418	410	433
Sulfur	ppm	ASTM D5185m	2500	794	937	1064
CONTAMINANTS	3	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>20	<1	0	0
Sodium	ppm	ASTM D5185m		0	0	0
Potassium	ppm	ASTM D5185m	>20	<1	0	1
FLUID CLEANLIN	IESS	method	limit/base	current	history1	history2
Particles >4μm		ASTM D7647		13964	4549	13440
Particles >6µm		ASTM D7647	>1300	<u> </u>	571	562
Particles >14μm		ASTM D7647	>160	45	26	16
Particles >21µm		ASTM D7647	>40	9	4	3
Particles >38μm		ASTM D7647	>10	0	0	0
Particles >71μm		ASTM D7647	>3	0	0	0
Oil Cleanliness		ISO 4406 (c)	>17/14	<b>18/13</b>	16/12	16/11
FLUID DEGRADA	ATION	method	limit/base	current	history1	history2
Acid Number (AN)	mg KOH/g	ASTM D8045	0.57	0.37	0.40	0.42




# **OIL ANALYSIS REPORT**









VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Yellow Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Precipitate	scalar	*Visual	NONE	NONE	NONE	NONE
Silt	scalar	*Visual	NONE	NONE	NONE	NONE
Debris	scalar	*Visual	NONE	NONE	NONE	NONE
Sand/Dirt	scalar	*Visual	NONE	NONE	NONE	NONE
Appearance	scalar	*Visual	NORML	NORML	NORML	NORML
Odor	scalar	*Visual	NORML	NORML	NORML	NORML
<b>Emulsified Water</b>	scalar	*Visual	>0.1	NEG	NEG	NEG
Free Water	scalar	*Visual		NEG	NEG	NEG

FLUID PROPER	HE5	metnoa	ilmit/base	current	nistory i	nistory
Visc @ 40°C	cSt	ASTM D445	32	43.7	43.7	44.2

SAMPLE IMAGES	method	limit/base	current	history1	history2

Color





GR	APHS							
Fer	rous All	oys					Particle Count	т26
8-	iron	ium					122,880 +	24
	nickel			٨		-1-1-1		
2-	~	^	$\sim$	-/	M	1	30,720	-22
0 L	/20	3/21	1777	/22	727	727	₹ 7,680	-20
Dec6/19	Apr4/20	Jan23/21	Jul22/21	Mar17/22	Jul25/22	Oct28/22	a 1,920 -	+20 +18 +16 +14 +12
	n-ferrou	s Met	als				1.920 - 1.920 - 480	-16
8 I	coppe	1					120 - 120 -	+14
6 -	manana lead	++					30-	-12
2							8 Sibresemal	10
0	/20	3/21	12/2	/22	/22	722	2	-8
Dec6/19	Apr4/20	Jan23/2	Jul22/2	Mar17/22	Jul25/22	Oct28/22	0	
	cosity @	40°	С				4μ 6μ 14μ 21μ Acid Number	38μ 71μ
45							⊋1.00 Abnormal	
40 - Abno	ormal	_				1	€ 0.60 - Base	
35 Base	ormal						O 20 Abnormal	
25				2	2	2	Abnormal  Abnormal  Abnormal  Abnormal  Abnormal  Abnormal	2
ec6/19	Apr4/20	ın23/2.	ul22/21	ar17/22	125/22	:128/22	lec6/19 hpr4/20 nn23/212 n17/22	1125/22





Certificate L2367

Laboratory Sample No. Lab Number Unique Number : 10324598 Test Package : MOB 2

: KL0009728 : 05759991

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received : 06 Feb 2023 Diagnosed Diagnostician : Doug Bogart

: 07 Feb 2023

7550 W I20 ODESSA, TX US 79763 Contact: MIKE COMBDEN

CITADEL DRILLING

mcombden@citadeldrilling.com T: (780)955-5509

To discuss this sample report, contact Customer Service at 1-800-237-1369. \* - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

F: