



PROBLEM SUMMARY

Sample Rating Trend



FUEL





Machine Id
CZM EK200 4160081 (S/N SAV0006)

Component
Diesel Engine

Fluid
DIESEL ENGINE OIL SAE 15W40 (10 GAL)

COMPONENT CONDITION SUMMARY



RECOMMENDATION

We advise that you check the fuel injection system. Oil and filter change at the time of sampling has been noted. We recommend an early resample to monitor this condition.

PROBLEMATIC TEST RESULTS

Sample Status				SEVERE	---	---
Fuel	%	ASTM D3524	>5	20.0	---	---
Visc @ 100°C	cSt	ASTM D445	14.4	4.59	---	---

Customer Id: HAYCOL
Sample No.: WC0641802
Lab Number: 05792442
Test Package: MOBCE



To manage this report scan the QR code

To discuss the diagnosis or test data:
Doug Bogart +1 (800)237-1369 x4016
dougb@wearcheckusa.com

To change component or sample information:
Customer Service +1 1-800-237-1369
customerservice@wearcheck.com




RECOMMENDED ACTIONS

Action	Status	Date	Done By	Description
Change Fluid	---	---	?	Oil and filter change at the time of sampling has been noted.
Change Filter	---	---	?	Oil and filter change at the time of sampling has been noted.
Resample	---	---	?	We recommend an early resample to monitor this condition.
Check Fuel/injector System	---	---	?	We advise that you check the fuel injection system.

HISTORICAL DIAGNOSIS











OIL ANALYSIS REPORT



VISUAL	method	limit/base	current	history1	history2
White Metal	scalar	*Visual	NONE	NONE	---
Yellow Metal	scalar	*Visual	NONE	NONE	---
Precipitate	scalar	*Visual	NONE	NONE	---
Silt	scalar	*Visual	NONE	NONE	---
Debris	scalar	*Visual	NONE	NONE	---
Sand/Dirt	scalar	*Visual	NONE	NONE	---
Appearance	scalar	*Visual	NORML	NORML	---
Odor	scalar	*Visual	NORML	NORML	---
Emulsified Water	scalar	*Visual	>0.2	NEG	---
Free Water	scalar	*Visual		NEG	---

FLUID PROPERTIES	method	limit/base	current	history1	history2
Visc @ 100°C	cSt	ASTM D445	14.4 ▲ 4.59	---	---

GRAPHS



Certificate L2367

Laboratory : WearCheck USA - 501 Madison Ave., Cary, NC 27513
Sample No. : WC0641802 **Received** : 15 Mar 2023
Lab Number : 05792442 **Diagnosed** : 15 Mar 2023
Unique Number : 10377113 **Diagnostician** : Doug Bogart
Test Package : MOBCE (Additional Tests: FuelDilution, PercentFuel, TBN)

KELLER-NA - KERNERSVILLE
 1024 EAST MOUNTAIN ST
 KERNERSVILLE, NC
 US 27284
 Contact: BRENT SHIRLEY
 BShirley@keller-na.com
 T: (336)992-2300
 F: (336)668-3259

To discuss this sample report, contact Customer Service at 1-800-237-1369.

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)