


#### Area WHEY [1718914] Machine Id RO07PP31BB01 Component

**IEA** 

Bearing Fluid MOBIL SHC 626 (--- GAL)

### COMPONENT CONDITION SUMMARY



#### RECOMMENDATION

No corrective action is recommended at this time. Resample at the next service interval to monitor.

PROBLEMATIC TEST RESULTS									
Sample Status		ABNORMAL	ABNORMAL	ABNORMAL					
Copper	ppm	ASTM D5185m	>20	<u> </u>	<b>4</b> 0	<b>4</b> 1			


Customer Id: LEPGRE Sample No.: WC0805871 Lab Number: 05833324 Test Package: IND 1



To manage this report scan the QR code

To discuss the diagnosis or test data: Angela Borella +1 800-237-1369 angela.borella@wearcheckusa.com

To change component or sample information: Customer Service +1 1-800-237-1369 customerservice@wearcheck.com



#### **RECOMMENDED ACTIONS**

There are no recommended actions for this sample.

#### HISTORICAL DIAGNOSIS

#### 23 Oct 2022 Diag: Don Baldridge



No corrective action is recommended at this time. Resample at the next service interval to monitor. The copper level is abnormal. All other component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.



view report

#### 27 Sep 2022 Diag: Don Baldridge



No corrective action is recommended at this time. Resample at the next service interval to monitor. The copper level is abnormal. All other component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

02 Nov 2021 Diag: Don Baldridge

#### NORMAL



Resample at the next service interval to monitor.All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.





## **OIL ANALYSIS REPORT**

Area WHEY [1718914] Machine Id RO07PP31BB01 Component

Bearing Fluid MOBIL SHC 626 (--- GAL)

#### DIAGNOSIS

#### A Recommendation

No corrective action is recommended at this time. Resample at the next service interval to monitor.

#### 🔺 Wear


The copper level is abnormal. All other component wear rates are normal.

#### Contamination

There is no indication of any contamination in the oil.

#### Fluid Condition

The condition of the oil is acceptable for the time in service.





SAMPLE INFORM	IATION	method	limit/base	current	history1	history2
Sample Number		Client Info		WC0805871	WC0745797	WC0678363
Sample Date		Client Info		21 Apr 2023	23 Oct 2022	27 Sep 2022
Machine Age	hrs	Client Info		0	0	0
Oil Age	hrs	Client Info		0	0	0
Oil Changed		Client Info		N/A	N/A	N/A
Sample Status				ABNORMAL	ABNORMAL	ABNORMAL
WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>20	1	2	1
Chromium	ppm	ASTM D5185m	>20	0	0	0
Nickel	ppm	ASTM D5185m	>20	0	0	0
Titanium	ppm	ASTM D5185m		0	0	0
Silver	ppm	ASTM D5185m		7	<1	0
Aluminum	ppm	ASTM D5185m	>20	0	<1	<1
Lead	ppm	ASTM D5185m	>20	2	5	5
Copper	ppm	ASTM D5185m	>20	<u> </u>	<b>4</b> 0	<b>4</b> 1
Tin	ppm	ASTM D5185m	>20	0	<1	<1
Antimony	ppm	ASTM D5185m				
Vanadium	ppm	ASTM D5185m		0	0	0
Cadmium	ppm	ASTM D5185m		0	0	0
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m		0	0	0
Barium	ppm	ASTM D5185m		0	0	0
Molybdenum	ppm	ASTM D5185m		0	0	0
Manganese	ppm	ASTM D5185m		<1	<1	<1
Magnesium	ppm	ASTM D5185m		0	0	0
Calcium	ppm	ASTM D5185m		26	25	27
Phosphorus	ppm	ASTM D5185m		867	826	868
Zinc	ppm	ASTM D5185m		833	797	853
Sulfur	ppm	ASTM D5185m		2062	2048	2129
CONTAMINANTS		method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>15	0	<1	<1
Sodium	ppm	ASTM D5185m		2	2	2
Potassium	ppm	ASTM D5185m	>20	0	1	1
VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Yellow Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Precipitate	scalar	*Visual	NONE	NONE	NONE	NONE
Silt	scalar	*Visual	NONE	NONE	NONE	NONE
Debris	scalar	*Visual	NONE	NONE	NONE	NONE
Sand/Dirt	scalar	*Visual	NONE	NONE	NONE	NONE
Appearance	scalar	*Visual	NORML	NORML	NORML	NORML
Odor	scalar	*Visual	NORML	NORML	NORML	NORML
Emulsified Water	scalar	*Visual	>2	NEG	NEG	NEG
Free Water	scalar	*Visual		NEG	NEG	NEG




# **OIL ANALYSIS REPORT**

#### 🔺 Non-ferrous Metals





#### GRAPHS



LEPRINO FOODS-GREELEY 1302 1ST AVE GREELEY, CO US 80631-5909 Contact: ERIC KLINE EKLINE@LEPRINOFOODS.COM T: 106:2012) F: (970)347-5190



 Certificate 12367
 Test Package
 : IND 1

 To discuss this sample report, contact Customer Service at 1-800-237-1369.
 EKL

 \* - Denotes test methods that are outside of the ISO 17025 scope of accreditation.
 Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

Diagnosed

: 02 May 2023

Diagnostician : Angela Borella

: 05833324

Laboratory

Sample No.

Lab Number

Unique Number : 10446817

Submitted By: MICHAEL VILLASENOR

Page 4 of 4