

OIL ANALYSIS REPORT

Sample Rating Trend



EHA FILL STATION

Transmission (Auto) Fluid ATF (--- GAL)

DIAGNOSIS

Recommendation

Resample at the next service interval to monitor.

Wear

All component wear rates are normal.

Contamination

The amount and size of particulates present in the system are acceptable. There is no indication of any contamination in the fluid.

Fluid Condition

The AN level is acceptable for this fluid. The condition of the fluid is suitable for further service.

Partic	le Filter	(Magn:	X)
		(· · · /



				10/2023		
SAMPLE INFORM	IATION	method	limit/base	current	history1	history2
Sample Number		Client Info		PH0000925		
Sample Date		Client Info		10 May 2023		
Machine Age	hrs	Client Info		0		
Oil Age	hrs	Client Info		0		
Oil Changed		Client Info		N/A		
Sample Status				NORMAL		
WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>160	0		
Chromium	ppm	ASTM D5185m	>5	0		
Nickel	ppm	ASTM D5185m	>5	0		
Titanium	ppm	ASTM D5185m		0		
Silver	ppm	ASTM D5185m	>5	0		
Aluminum	ppm	ASTM D5185m	>50	3		
Lead	ppm	ASTM D5185m	>50	0		
Copper	ppm	ASTM D5185m	>225	0		
Tin	ppm	ASTM D5185m	>10	0		
Vanadium	ppm	ASTM D5185m		0		
Cadmium	ppm	ASTM D5185m		0		
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m		60		
Barium	ppm	ASTM D5185m		0		
Molybdenum	ppm	ASTM D5185m		0		
Manganese	ppm	ASTM D5185m		<1		
Magnesium	ppm	ASTM D5185m		2		
Calcium	ppm	ASTM D5185m		8		
Phosphorus	ppm	ASTM D5185m		158		
Zinc	ppm	ASTM D5185m		0		
Sulfur	ppm	ASTM D5185m		587		
CONTAMINANTS		method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>20	<1		
Sodium	ppm	ASTM D5185m		0		
Potassium	ppm	ASTM D5185m	>20	0		
FLUID CLEANLIN	ESS	method	limit/base	current	history1	history2
Particles >4µm		ASTM D7647	>10000	182		
Particles >6µm		ASTM D7647	>2500	27		
Particles >14µm		ASTM D7647	>320	5		
Particles >21µm		ASTM D7647	>80	1		
Particles >38µm		ASTM D7647	>20	0		
Particles >71µm		ASTM D7647	>4	0		
Oil Cleanliness		ISO 4406 (c)	>20/18/15	15/12/10		
FLUID DEGRADA	TION	method	limit/base	current	history1	history2
Acid Number (AN)	ma KOH/a	ASTM D8045		0.65		



number of particles (per 1

OIL ANALYSIS REPORT



Laboratory : WearCheck USA - 501 Madison Ave., Cary, NC 27513 PARKER HANNIFIN Sample No. : PH0000925 Received : 15 May 2023 5520 HWY 169 N Lab Number NEW HOPE, MN :05847100 Diagnosed : 18 May 2023 : 10471207 Diagnostician : Doug Bogart US 55428 Unique Number Test Package : PLANT (Additional Tests: KF) Contact: MATT DALEO Certificate L2367 matthew.daleo@parker.com To discuss this sample report, contact Customer Service at 1-800-237-1369. T: * - Denotes test methods that are outside of the ISO 17025 scope of accreditation. F:

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

Contact/Location: MATT DALEO - PARNEWMN

no image

no image

no image

no image

no image

no image