

# **OIL ANALYSIS REPORT**

Area **21**Machine Id **A21 R20** 

**Agitator Gearbox** 

**GEAR LIFE 220 (2 GAL)** 

Sample Rating Trend



## Recommendation

Resample at the next service interval to monitor.

All component wear rates are normal.

### Contamination

There is no indication of any contamination in the


## **Fluid Condition**


The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.


		un2018 Mar20	19 Feb2020 Sep2020 Ma	ar2021 Nov2021 Mar2022 Aug2022	Mar2023	
SAMPLE INFORM	IATION	method	limit/base	current	history1	history2
Sample Number		Client Info		HPL0002802	HPL0001766	HPL0001731
Sample Date		Client Info		16 May 2023	09 Mar 2023	06 Dec 2022
Machine Age	hrs	Client Info		0	0	0
Oil Age	hrs	Client Info		10080	7920	5760
Oil Changed		Client Info		Not Changd	Not Changd	Not Changd
Sample Status				NORMAL	NORMAL	NORMAL
WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>150	1	<1	2
Chromium	ppm	ASTM D5185m	>10	0	<1	0
Nickel	ppm	ASTM D5185m	>10	0	<1	0
Titanium	ppm	ASTM D5185m		0	<1	0
Silver	ppm	ASTM D5185m		0	<1	0
Aluminum	ppm	ASTM D5185m	>25	2	3	4
Lead	ppm	ASTM D5185m	>100	0	0	<1
Copper	ppm	ASTM D5185m	>50	0	<1	5
Tin	ppm	ASTM D5185m	>10	0	0	0
Vanadium	ppm	ASTM D5185m		0	<1	0
Cadmium	ppm	ASTM D5185m		0	0	0
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m		0	0	0
Barium	ppm	ASTM D5185m		0	0	0
Molybdenum	ppm	ASTM D5185m		0	<1	0
Manganese	ppm	ASTM D5185m		0	1	0
Magnesium	ppm	ASTM D5185m		<1	5	3
Calcium	ppm	ASTM D5185m		7	7	10
Phosphorus	ppm	ASTM D5185m		155	154	159
Zinc	ppm	ASTM D5185m		232	217	248
Sulfur	ppm	ASTM D5185m		19982	21565	22309
CONTAMINANTS		method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>50	<1	<1	0
Sodium	ppm	ASTM D5185m		0	<1	0
Potassium	ppm	ASTM D5185m	>20	<1	1	0
FLUID DEGRADA	TION	method	limit/base	current	history1	history2
Acid Number (AN)	mg KOH/g	ASTM D8045		0.31	0.34	0.35
VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Yellow Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Precipitate	scalar	*Visual	NONE	NONE	NONE	NONE
Silt	scalar	*Visual	NONE	NONE	NONE	NONE
Debris	scalar	*Visual	NONE	NONE	NONE	NONE
Sand/Dirt	scalar	*Visual	NONE	NONE	NONE	NONE
Appearance	scalar	*Visual	NORML	NORML	NORML	NORML
Odor	scalar	*Visual	NORML	NORML	NORML	NORML
Emulsified Water	scalar	*Visual	>0.1	NEG	NEG	NEG
Free Water	scalar	*Visual		NEG	NEG	NEG
0:10:47\ Dov: 1					Cubmitted D	. TIM LITIDEDT



# **OIL ANALYSIS REPORT**







100



Certificate L2367

Laboratory Sample No. Lab Number **Unique Number** 

: HPL0002802 : 05853980 : 10483335 Test Package : MOB 2

150

[ 100

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received : 22 May 2023 Diagnosed

: 23 May 2023 Diagnostician : Wes Davis

**KENSING** 2525 S KENSINGTON RD KANKAKEE, IL

US 60901 Contact: TIM HUBERT

timothy.hubert@kensingsolutions.com T: (815)939-8918

To discuss this sample report, contact Customer Service at 1-800-237-1369.

\* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

F: x: