


# **PROBLEM SUMMARY**

## Fermentation Machine Id ABON FFG11AB01 Mixing Tank, Agitator Component

Gearbox Fluid JAX FGG-AW ISO 220 (24 GAL)

### COMPONENT CONDITION SUMMARY



### RECOMMENDATION

No corrective action is recommended at this time. Resample at the next service interval to monitor.

M i							
PROBLEMATIC TEST RESULTS							
Sample Status			ABNORMAL	ABNORMAL	ABNORMAL		
Particles >4µm	ASTM D7647	>20000	<u> </u>	<b>46168</b>	<u> </u>		
Particles >6µm	ASTM D7647	>5000	<u> </u>	2873	4017		
Oil Cleanliness	ISO 4406 (c)	>21/19/16	<u> </u>	<b>a</b> 23/19/13	<b>A</b> 23/19/13		


Customer Id: NOVFRANC Sample No.: WC0793892 Lab Number: 05878078 Test Package: IND 2



To manage this report scan the QR code

*To discuss the diagnosis or test data:* Doug Bogart +1 (800)237-1369 x4016 <u>dougb@wearcheckusa.com</u>

To change component or sample information: Customer Service +1 1-800-237-1369 customerservice@wearcheck.com



### **RECOMMENDED ACTIONS**

There are no recommended actions for this sample.

### HISTORICAL DIAGNOSIS

#### 08 Dec 2022 Diag: Jonathan Hester



No corrective action is recommended at this time. Resample at the next service interval to monitor.All component wear rates are normal. There is a high amount of silt (particulates < 6 microns in size) present in the oil. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.



#### 27 May 2022 Diag: Doug Bogart

No corrective action is recommended at this time. Resample at the next service interval to monitor.All component wear rates are normal. There is a high amount of silt (particulates < 6 microns in size) present in the oil. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.





06 Dec 2021 Diag: Doug Bogart

No corrective action is recommended at this time. Resample at the next service interval to monitor.All component wear rates are normal. There is a moderate amount of silt (particulates < 6 microns in size) present in the oil. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.





## **OIL ANALYSIS REPORT**

## **Fermentation ÄBON FFG11AB01 Mixing Tank, Agitator** Component

Gearbox

Fluid JAX FGG-AW ISO 220 (24 GAL)

### DIAGNOSIS

### Recommendation

No corrective action is recommended at this time. Resample at the next service interval to monitor.

### Wear


All component wear rates are normal.

### Contamination

There is a high amount of silt (particulates < 14 microns in size) present in the oil.

### Fluid Condition

The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.




SAMPLE INFORM	MATION	method	limit/base	current	history 1	history 2
Sample Number		Client Info		WC0793892	WC0741049	WC0688788
Sample Date		Client Info		16 Jun 2023	08 Dec 2022	27 May 2022
Machine Age	hrs	Client Info		0	0	0
Oil Age	hrs	Client Info		0	0	0
Oil Changed		Client Info		N/A	N/A	N/A
Sample Status				ABNORMAL	ABNORMAL	ABNORMAL
WEAR METALS		method	limit/base		history 1	history 2
Iron	ppm	ASTM D5185m	>200	5	4	3
Chromium	ppm	ASTM D5185m		0	0	0
Nickel	ppm	ASTM D5185m	>15	0	0	0
Titanium	ppm	ASTM D5185m		<1	0	0
Silver	ppm	ASTM D5185m		0	0	0
Aluminum	ppm	ASTM D5185m	>25	<1	0	0
Lead	ppm	ASTM D5185m	>100	0	0	0
Copper	ppm	ASTM D5185m	>200	<1	0	0
Tin	ppm	ASTM D5185m	>25	0	0	0
Antimony	ppm	ASTM D5185m	>5			
Vanadium	ppm	ASTM D5185m		0	0	0
Cadmium	ppm	ASTM D5185m		<1	0	0
ADDITIVES		method	limit/base	current	history 1	history 2
			in the base			
Boron	ppm	ASTM D5185m		<1	2	0
Barium	ppm	ASTM D5185m		0	4	0
Molybdenum	ppm	ASTM D5185m		0	0	0
Manganese	ppm	ASTM D5185m		<1	0	<1
Magnesium	ppm	ASTM D5185m		<1	0	0
Calcium	ppm	ASTM D5185m		67	58	60
Phosphorus	ppm	ASTM D5185m		590	558	576
Zinc	ppm	ASTM D5185m		0	<1	<1
Sulfur	ppm	ASTM D5185m		709	429	717
CONTAMINANTS	6	method	limit/base	current	history 1	history 2
Silicon	ppm	ASTM D5185m	>50	6	7	7
Sodium	ppm	ASTM D5185m		<1	0	<1
Potassium	ppm	ASTM D5185m	>20	0	0	0
Water	%	ASTM D6304		0.005	0.005	0.004
ppm Water	ppm	ASTM D6304		52.9	56.9	49.3
FLUID CLEANLIN		method	limit/base	current	history 1	history 2
Particles >4µm		ASTM D7647	>20000	▲ 54044	46168	▲ 68810
Particles >6µm		ASTM D7647	>5000	<u> </u>	2873	4017
Particles >14µm		ASTM D7647	>640	224	47	79
Particles >21µm		ASTM D7647 ASTM D7647	>160	47	7	7
Particles >38µm		ASTM D7647 ASTM D7647	>40	2	1	0
		ASTM D7647 ASTM D7647			0	
Particles >71µm				0		0
Oil Cleanliness		ISO 4406 (c)	>21/19/16	<b>23/20/15</b>	▲ 23/19/13	▲ 23/19/13
FLUID DEGRADA	ATION	method	limit/base		history 1	history 2
Acid Number (AN)	mg KOH/g	ASTM D8045		0.56	0.60	0.63
1.41.08) Bov: 1					Submitted By:	CHASE MODE


Acid Number (AN) Report Id: NOVFRANC [WUSCAR] 05878078 (Generated: 07/12/2023 10:41:08) Rev: 1


Submitted By: CHASE MCGEE



# **OIL ANALYSIS REPORT**








VISUAL		method	limit/base	current	history 1	history 2
White Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Yellow Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Precipitate	scalar	*Visual	NONE	NONE	NONE	NONE
Silt	scalar	*Visual	NONE	NONE	NONE	NONE
Debris	scalar	*Visual	NONE	LIGHT	NONE	NONE
Sand/Dirt	scalar	*Visual	NONE	NONE	NONE	NONE
Appearance	scalar	*Visual	NORML	NORML	NORML	NORML
Odor	scalar	*Visual	NORML	NORML	NORML	NORML
Emulsified Water	scalar	*Visual	>0.2	NEG	NEG	NEG
Free Water	scalar	*Visual		NEG	NEG	NEG
FLUID PROPERT	IES	method	limit/base	current	history 1	history 2
Visc @ 40°C	cSt	ASTM D445	220	212	211	213
SAMPLE IMAGES	S	method	limit/base	current	history 1	history 2
Color						

Bottom



Report Id: NOVFRANC [WUSCAR] 05878078 (Generated: 07/12/2023 10:41:08) Rev: 1

Submitted By: CHASE MCGEE

Page 4 of 4