

# **PROBLEM SUMMARY**

Sample Rating Trend


WEAR

Machine Id **8362**Component

**Left Final Drive** 

GEAR OIL SAE 80W140 (--- GAL)

### **COMPONENT CONDITION SUMMARY**



### RECOMMENDATION

The oil change at the time of sampling has been noted. No corrective action is recommended at this time. Resample at the next service interval to monitor.

PROBLEMATIC TEST RESULTS								
Sample Status				ABNORMAL	ABNORMAL	NORMAL		
Copper	ppm	ASTM D5185m	>50	<b>^</b> 65	<u>▲</u> 57	31		

Customer Id: TRANEW Sample No.: WC0831231 Lab Number: 05898942 Test Package: CONST

To manage this report scan the QR code

To discuss the diagnosis or test data:

Don Baldridge +1 don.b505@comcast.net

To change component or sample information: Customer Service +1 1-800-237-1369 customerservice@wearcheck.com

### **RECOMMENDED ACTIONS**

There are no recommended actions for this sample.

### HISTORICAL DIAGNOSIS

## 14 Feb 2023 Diag: Don Baldridge

WEAR



The oil change at the time of sampling has been noted. No corrective action is recommended at this time. Resample at the next service interval to monitor. The copper level is abnormal. All other component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.



#### 27 Dec 2022 Diag: Sean Felton

NORMAL



Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.



### 29 Nov 2022 Diag: Don Baldridge

WEAR




The oil change at the time of sampling has been noted. No corrective action is recommended at this time. Resample at the next service interval to monitor. The copper level is abnormal. All other component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.





# **OIL ANALYSIS REPORT**

**Sample Rating Trend** 



WEAR



Machine Id
8362
Component
Left Final Dri

**Left Final Drive** 

GEAR OIL SAE 80W140 (--- GAL)

# DIAGNOSIS

#### Recommendation

The oil change at the time of sampling has been noted. No corrective action is recommended at this time. Resample at the next service interval to monitor.

## Wear

The copper level is abnormal. All other component wear rates are normal.

#### Contamination

There is no indication of any contamination in the

### **Fluid Condition**

The condition of the oil is acceptable for the time in service.

		Aar2012 Dec2	012 May2013 Mar2015	Feb 2022 Apr 2022 Nov2022	Feb2023	
SAMPLE INFORM	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		WC0831231	WC0775993	WC0751109
Sample Date		Client Info		12 Jul 2023	14 Feb 2023	27 Dec 2022
Machine Age	hrs	Client Info		8619	7228	6609
Oil Age	hrs	Client Info		237	619	295
Oil Changed		Client Info		Changed	Changed	Changed
Sample Status				ABNORMAL	ABNORMAL	NORMAL
WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>500	67	60	63
Chromium	ppm	ASTM D5185m	>10	1	0	<1
Nickel	ppm	ASTM D5185m	>10	2	2	2
Titanium	ppm	ASTM D5185m		<1	<1	1
Silver	ppm	ASTM D5185m		0	0	0
Aluminum	ppm	ASTM D5185m	>25	6	12	15
Lead	ppm	ASTM D5185m	>25	0	0	0
Copper	ppm	ASTM D5185m	>50	<u>^</u> 65	<b>▲</b> 57	31
Tin	ppm	ASTM D5185m	>10	4	2	2
Vanadium	ppm	ASTM D5185m		0	0	0
Cadmium	ppm	ASTM D5185m		0	0	0
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m	400	155	166	55
Barium	ppm	ASTM D5185m	200	0	0	1
Molybdenum	ppm	ASTM D5185m	12	<1	0	<1
Manganese	ppm	ASTM D5185m		1	1	<1
Magnesium	ppm	ASTM D5185m	12	2	5	6
Calcium	ppm	ASTM D5185m	150	220	211	770
Phosphorus	ppm	ASTM D5185m	1650	395	341	430
Zinc	ppm	ASTM D5185m	125	52	62	206
Sulfur	ppm	ASTM D5185m	22500	2694	1633	2113
CONTAMINANTS		method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>75	43	68	71
Sodium	ppm	ASTM D5185m		<1	<1	0
Potassium	ppm	ASTM D5185m	>20	2	1	4
VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	*Visual	NONE	NONE	NONE	MODER
Yellow Metal	scalar	*Visual	NONE	MODER	MODER	NONE
Precipitate	scalar	*Visual	NONE	NONE	NONE	NONE
Silt	scalar	*Visual	NONE	NONE	NONE	NONE
Debris	scalar	*Visual	NONE	NONE	NONE	NONE
Sand/Dirt	scalar	*Visual	NONE	NONE	NONE	NONE
Appearance	scalar	*Visual	NORML	NORML	NORML	NORML
Odor	scalar	*Visual	NORML	NORML	NORML	NORML
Emulsified Water	scalar	*Visual	>0.2	NEG	NEG	NEG
Free Water	scalar	*Visual		NEG	NEG	NEG
FLUID PROPERT	IES	method	limit/base	current	history1	history2

Visc @ 40°C

cSt

ASTM D445 263


107

Contact/Location: MIKE WYATT - TRANEW

110





# **OIL ANALYSIS REPORT**




SAMPLE IMAGES	method	limit/base	current	history1	history2
Color			no image	no image	no image
Bottom			no image	no image	no image

# Viscosity @ 40°C 350 © 250 ₹ 200 150











Certificate L2367

Laboratory Sample No. Lab Number Unique Number : 10560298 Test Package : CONST

: WC0831231 : 05898942

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received : 14 Jul 2023 Diagnosed : 17 Jul 2023 Diagnostician : Don Baldridge

TRADER CONSTRUCTION CO.

PO DRAWER 1578 NEW BERN, NC US 28563

Contact: MIKE WYATT mwyatt@traderconstruction.com

T: (252)633-1399 F: (252)638-4871

To discuss this sample report, contact Customer Service at 1-800-237-1369.

\* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)