


OIL ANALYSIS REPORT

Sample Rating Trend







060

OKLAHOMA/3/EG - TRUCK-OFF-HWY-HEAVY HAUL Machine Id 69.79L [OKLAHOMA^3^EG - TRUCK-OFF-HWY-HEAVY HAUL]

Component
Front Left Final Drive

MOBIL SHC 629 (--- GAL)

DIAGNOSIS

Recommendation

Resample at the next service interval to monitor.

Wear

All component wear rates are normal.

Contamination

There is no indication of any contamination in the oil


Fluid Condition

The condition of the oil is acceptable for the time in service.


~L)		Jun2016	Nov2017 Jan2019	May2020 Jul2021	Jul2023	
SAMPLE INFORM	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		WC0821762	WC0758762	WC0578368
Sample Date		Client Info		07 Jul 2023	23 Nov 2022	01 Jul 2021
Machine Age	hrs	Client Info		19339	18661	16644
Oil Age	hrs	Client Info		15912	15912	732
Oil Changed		Client Info		N/A	N/A	Not Changd
Sample Status				NORMAL	NORMAL	NORMAL
WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>800	28	38	40
Chromium	ppm	ASTM D5185m	>10	<1	<1	<1
Nickel	ppm	ASTM D5185m	>5	<1	2	<1
Titanium	ppm	ASTM D5185m	>15	0	0	0
Silver	ppm	ASTM D5185m	>2	0	0	0
Aluminum	ppm	ASTM D5185m	>75	<1	3	<1
Lead	ppm	ASTM D5185m	>10	0	0	0
Copper	ppm	ASTM D5185m	>75	11	15	18
Tin	ppm	ASTM D5185m	>8	<1	<1	<1
Antimony	ppm	ASTM D5185m	>50			0
Vanadium	ppm	ASTM D5185m		0	0	0
Cadmium	ppm	ASTM D5185m		0	0	0
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m		1	3	8
Barium	ppm	ASTM D5185m		0	0	0
Molybdenum	ppm	ASTM D5185m		0	0	<1
Manganese	ppm	ASTM D5185m		<1	<1	<1
Magnesium	ppm	ASTM D5185m		2	3	2
Calcium	ppm	ASTM D5185m		109	175	146
Phosphorus	ppm	ASTM D5185m		533	466	572
Zinc	ppm	ASTM D5185m		43	53	48
Sulfur	ppm	ASTM D5185m		4643	3836	3910
CONTAMINANTS	;	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>400	31	31	29
Sodium	ppm	ASTM D5185m		<1	1	1
Potassium	ppm	ASTM D5185m	>20	<1	0	0
VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Yellow Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Precipitate	scalar	*Visual	NONE	NONE	NONE	NONE
Silt	scalar	*Visual	NONE	NONE	NONE	NONE
Debris	scalar	*Visual	NONE	NONE	NONE	NONE
Sand/Dirt	scalar	*Visual	NONE	NONE	NONE	NONE
Appearance	scalar	*Visual	NORML	NORML	NORML	NORML
Odor	scalar	*Visual	NORML	NORML	NORML	NORML
Emulsified Water	scalar	*Visual	>0.2	NEG	NEG	NEG
Free Water	scalar	*Visual		NEG	NEG	NEG





OIL ANALYSIS REPORT



Visc @ 40°C cSt ASTM D445 142.8 155 152 157 SAMPLE IMAGES method limit/base current history1 his Color no image no image no image	tory2
	tory2
Color no image no image no in	
	nage
Bottom no image no image no in	nage











Laboratory Sample No. Lab Number Unique Number : 10560310 Test Package : CONST

: WC0821762 : 05898954

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received : 14 Jul 2023 Diagnosed : 17 Jul 2023 Diagnostician : Don Baldridge

SHERWOOD CONSTRUCTION CO INC

3219 WEST MAY ST WICHITA, KS US 67213 Contact: DOUG KING

doug.king@sherwood.net T: (316)617-3161

To discuss this sample report, contact Customer Service at 1-800-237-1369. * - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

F: x: