

No relevant graphs to display

RECOMMENDATION

Resample at the next service interval to monitor.

PROBLEMATIC TEST RESULTS							
Sample Status				ABNORMAL	ABNORMAL	ABNORMAL	
Debris	scalar	*Visual	NONE	A MODER	NONE	LIGHT	

Customer Id: SIEKAN Sample No.: WC0811650 Lab Number: 05899484 Test Package: IND 1



To manage this report scan the QR code

To discuss the diagnosis or test data: Angela Borella +1 800-237-1369 angela.borella@wearcheckusa.com

To change component or sample information: Customer Service +1 1-800-237-1369 customerservice@wearcheck.com

RECOMMENDED ACTIONS

There are no recommended actions for this sample.

HISTORICAL DIAGNOSIS

16 Sep 2022 Diag: Jonathan Hester



No corrective action is recommended at this time. Resample at the next service interval to monitor. Bearing and/or bushing wear is indicated. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

12 Jul 2022 Diag: Don Baldridge

No corrective action is recommended at this time. Resample at the next service interval to monitor. The lead level has decreased, but is still abnormal. All other component wear rates are normal. Moderate concentration of visible

dirt/debris present in the oil. The condition of the oil is acceptable for the time in service.





view report



28 Mar 2022 Diag: Angela Borella

We advise that you inspect for the source(s) of wear. Resample at the next service interval to monitor.Bearing and/or bushing wear is indicated. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.







OIL ANALYSIS REPORT

Area **Mixing Banbury Upstairs** Machine Id **BB05 (S/N TPK-019)** Component

Outboard Bearing Fluid R&O OIL ISO 68 (1 Kg)

DIAGNOSIS

Recommendation

Resample at the next service interval to monitor.

Wear


All component wear rates are normal.

Contamination

Moderate concentration of visible dirt/debris present in the oil.

Fluid Condition

The condition of the oil is acceptable for the time in service.




SAMPLE INFORM	ATION	method	limit/base	current	history1	history2
Sample Number		Client Info		WC0811650	WC0680120	WC0680158
Sample Date		Client Info		07 Jul 2023	16 Sep 2022	12 Jul 2022
Machine Age	hrs	Client Info		0	0	0
Oil Age	hrs	Client Info		0	0	0
Oil Changed		Client Info		N/A	N/A	N/A
Sample Status				ABNORMAL	ABNORMAL	ABNORMAL
WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>20	<1	8	6
Chromium	ppm	ASTM D5185m	>20	0	0	0
Nickel	ppm	ASTM D5185m	>20	0	0	0
Titanium	ppm	ASTM D5185m		0	0	0
Silver	ppm	ASTM D5185m		0	0	0
Aluminum	ppm	ASTM D5185m	>20	<1	<1	<1
Lead	ppm	ASTM D5185m	>20	9	4 5	4 9
Copper	ppm	ASTM D5185m	>20	1	5	4
Tin	ppm	ASTM D5185m	>20	2	<u> </u>	17
Vanadium	ppm	ASTM D5185m		<1	0	0
Cadmium	ppm	ASTM D5185m		0	0	0
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m	5	0	0	0
Barium	ppm	ASTM D5185m	5	0	0	4
Molybdenum	ppm	ASTM D5185m	5	0	0	0
Manganese	ppm	ASTM D5185m		0	<1	<1
Magnesium	ppm	ASTM D5185m	5	<1	0	0
Calcium	ppm	ASTM D5185m	5	<1	<1	2
Phosphorus	ppm	ASTM D5185m	100	6	13	8
Zinc	ppm	ASTM D5185m	25	0	4	7
Sulfur	ppm	ASTM D5185m	1500	2049	2076	2047
CONTAMINANTS		method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>15	<1	<1	0
Sodium	ppm	ASTM D5185m		<1	<1	0
Potassium	ppm	ASTM D5185m	>20	0	0	0
VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	*Visual	NONE	NONE	LIGHT	NONE
Yellow Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Precipitate	scalar	*Visual	NONE	NONE	NONE	NONE
Silt	scalar	*Visual	NONE	NONE	NONE	NONE
Debris	scalar	*Visual	NONE	A MODER	NONE	LIGHT
Sand/Dirt	scalar	*Visual	NONE	NONE	NONE	NONE
Appearance	scalar	*Visual	NORML	NORML	NORML	NORML
Odor	scalar	*Visual	NORML	NORML	NORML	NORML
Emulsified Water	scalar	*Visual	>2	NEG	NEG	NEG
Free Water	scalar	*Visual		NEG	NEG	NEG
FLUID PROPERT	IES	method	limit/base	current	history1	history2
Visc @ 40°C	cSt	ASTM D445	68	69.4	69.2	68.2


Report Id: SIEKAN [WUSCAR] 05899484 (Generated: 07/18/2023 18:34:35) Rev: 1



OIL ANALYSIS REPORT



SAMPLE IMAGES	method	limit/base	current	history1	history2
Color			no image	no image	
Bottom			no image	no image	



SIEMENS INDUSTRY INC. 4140 E. FRONT ST. KANSAS CITY, MO US 64120 Contact: Dave Wisemore david.wisemore@siemens.com T: (816)241-5544 012) F: x:



Laboratory Sample No. Lab Number Unique Number

 Certificate L2367
 Test Package
 IND 1

 To discuss this sample report, contact Customer Service at 1-800-237-1369.
 description

 * - Denotes test methods that are outside of the ISO 17025 scope of accreditation.
 description

 Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

Submitted By: Dave Wisemore

Page 4 of 4