


OIL ANALYSIS REPORT

Sample Rating Trend



NORMAL



6 MOTOR FRONT 6 MOTOR FRONT

Component

Bearing

ROYAL PURPLE SYNFILM 32 (--- GAL)

Recommendation

Resample at the next service interval to monitor.

All component wear rates are normal.

Contamination

There is no indication of any contamination in the

Fluid Condition

The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.

		Jul2019 Sep	2019 Mar2022 Dec2022	Jan 2023 Feb 2023 Mar 2023 Jun 2	1023 Jul2023	
SAMPLE INFORM	IATION	method	limit/base	current	history1	history2
Sample Number		Client Info		RP0018373	RP0018378	RP0020584
Sample Date		Client Info		16 Jul 2023	08 Jun 2023	08 Mar 2023
Machine Age	hrs	Client Info		0	0	0
Oil Age	hrs	Client Info		0	0	0
Oil Changed		Client Info		N/A	N/A	N/A
Sample Status				NORMAL	NORMAL	NORMAL
WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>20	0	0	<1
Chromium	ppm	ASTM D5185m	>20	0	0	0
Nickel	ppm	ASTM D5185m	>20	0	0	0
Titanium	ppm	ASTM D5185m		0	0	0
Silver	ppm	ASTM D5185m		0	0	0
Aluminum	ppm	ASTM D5185m	>20	<1	0	<1
Lead	ppm	ASTM D5185m	>20	13	10	14
Copper	ppm	ASTM D5185m	>20	3	3	12
Tin	ppm	ASTM D5185m	>20	2	3	5
Vanadium	ppm	ASTM D5185m		<1	0	0
Cadmium	ppm	ASTM D5185m		0	0	0
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m		0	0	0
Barium	ppm	ASTM D5185m		0	0	0
Molybdenum	ppm	ASTM D5185m		0	0	0
Manganese	ppm	ASTM D5185m		0	0	0
Magnesium	ppm	ASTM D5185m	90	65	56	36
Calcium	ppm	ASTM D5185m		0	<1	<1
Phosphorus	ppm	ASTM D5185m		11	15	15
Zinc	ppm	ASTM D5185m		15	25	12
CONTAMINANTS		method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>15	<1	<1	<1
Sodium	ppm	ASTM D5185m		0	1	0
Potassium	ppm	ASTM D5185m	>20	<1	<1	<1
Water	%	ASTM D6304	>2	0.018	0.015	0.016
ppm Water	ppm	ASTM D6304		188.6	153.7	163.7
FLUID DEGRADA	TION	method	limit/base	current	history1	history2
Acid Number (AN)	mg KOH/g	ASTM D8045		0.33	0.31	0.29
VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Yellow Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Precipitate	scalar	*Visual	NONE	NONE	NONE	NONE
Silt	scalar	*Visual	NONE	NONE	NONE	NONE
Debris	scalar	*Visual	NONE	NONE	NONE	NONE
Sand/Dirt	scalar	*Visual	NONE	NONE	NONE	NONE
Appearance	scalar	*Visual	NORML	NORML	NORML	NORML
Odor	scalar	*Visual	NORML	NORML	NORML	NORML
Emulsified Water	scalar	*Visual	>2	NEG	NEG	NEG
					DVA AAA ED AAA	41 15 1: . E 5 1 E 5 4 6 5 4


DYNAGFRANKLINNEGIEMAY

NEG

scalar *Visual



OIL ANALYSIS REPORT







Laboratory Sample No.

Lab Number Unique Number Test Package : IND 2

: RP0018373 : 05900012 : 10561368

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received : 17 Jul 2023 Diagnosed : 18 Jul 2023

Diagnostician : Don Baldridge

ENERGY TRANSFER - MAYPEARL 15230 FM 916

MAYPEARL, TX US 76064

Contact: DYLAN FRANKLIN

dylan.franklin@energytransfer.com T:

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

To discuss this sample report, contact Customer Service at 1-800-237-1369.

Report Id: ENEMAY [WUSCAR] 05900012 (Generated: 07/18/2023 14:48:40) Rev: 1

Contact/Location: DYLAN FRANKLIN - ENEMAY

F: