

#### **PROBLEM SUMMARY**

## LFC-1030-CM-01-CM029 Machine Id EX11MT02-1030 - EXTRUDER DRIVE 11\_2

Component **Gearbox** 

LE 4220 (13 QTS)





#### **COMPONENT CONDITION SUMMARY**

No relevant graphs to display

#### RECOMMENDATION

Resample at the next service interval to monitor.

PROBLEMATIC T	EST RE	SULTS				
Sample Status				ABNORMAL	NORMAL	NORMAL
Debris	scalar	*Visual	NONE	▲ MODER	VLITE	NONE

Customer Id: LEPALL Sample No.: WC0823777 Lab Number: 05900104 Test Package: IND 2

To manage this report scan the QR code

To discuss the diagnosis or test data: Angela Borella +1 800-237-1369 angela.borella@wearcheckusa.com

To change component or sample information: Customer Service +1 1-800-237-1369 customerservice@wearcheck.com

#### **RECOMMENDED ACTIONS**

There are no recommended actions for this sample.

#### HISTORICAL DIAGNOSIS

#### 05 Jan 2023 Diag: Wes Davis

NORMAL



Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.



#### 04 Jul 2022 Diag: Wes Davis

NORMAL



Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.



#### 07 Jan 2022 Diag: Wes Davis

NORMAL



Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.





### **OIL ANALYSIS REPORT**

#### Sample Rating Trend

#### VIS DEBRIS

history2

# LFC-1030-CM-01-CM029 Machine Id EX11MT02-1030 - EXTRUDER DRIVE 11\_2

Component

Gearbox

LE 4220 (13 QTS)

#### Fluid

#### ▲ Recommendation

**DIAGNOSIS** 

Resample at the next service interval to monitor.

#### Wear

All component wear rates are normal.

#### Contamination

Moderate concentration of visible dirt/debris present in the oil.

#### **Fluid Condition**


The AN level is acceptable for this fluid. The condition of the oil is acceptable for the time in service.


Sample Number	Client Info	wc	<b>0823777</b>	WC076
SAMPLE INFORMATION	method	limit/base	current	his
R DRIVE 11_2	v2008 Feb2010	Jan2012 Jan2014 Jan2016	Jan2018 Jan2020	Jan2022
•·• · · · · · · · · · · · · · · · · · ·				1 1 1 1


Sample Number		Client Info		WC0823777	WC0767393	WC0694335
Sample Date		Client Info		13 Jul 2023	05 Jan 2023	04 Jul 2022
Machine Age	days	Client Info		0	0	0
Oil Age	days	Client Info		0	0	0
Oil Changed		Client Info		N/A	N/A	N/A
Sample Status				ABNORMAL	NORMAL	NORMAL
WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>200	50	5	4
Chromium	ppm	ASTM D5185m	>15	<1	0	0
Nickel	ppm	ASTM D5185m	>15	0	0	0
Titanium	ppm	ASTM D5185m		0	0	0
Silver	ppm	ASTM D5185m		0	0	<1
Aluminum	ppm	ASTM D5185m	>25	<1	0	1
Lead	ppm	ASTM D5185m	>100	0	0	<1
Copper	ppm	ASTM D5185m	>200	<1	1	<1
Tin	ppm	ASTM D5185m	>25	0	0	<1
Antimony	ppm	ASTM D5185m	>5			
Vanadium	ppm	ASTM D5185m		<1	0	0
Cadmium	ppm	ASTM D5185m		0	0	<1
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m		0	21	20
Barium	ppm	ASTM D5185m		0	0	4
Molybdenum	ppm	ASTM D5185m		0	0	0
Manganese	ppm	ASTM D5185m		<1	<1	<1
Magnesium	ppm	ASTM D5185m		2	0	<1
Calcium	ppm	ASTM D5185m		1	0	<1
Phosphorus	ppm	ASTM D5185m		198	340	297
Zinc	ppm	ASTM D5185m		11	0	7
Sulfur	ppm	ASTM D5185m		2287	19897	16256
CONTAMINANTS		method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>50	2	<1	<1
Sodium	ppm	ASTM D5185m		2	<1	0
Potassium	ppm	ASTM D5185m	>20	1	<1	1
FLUID DEGRADA	TION	method	limit/base	current	history1	history2
Acid Number (AN)	mg KOH/g	ASTM D8045		0.50	0.80	0.78
VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Yellow Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Precipitate	scalar	*Visual	NONE	NONE	NONE	NONE
Silt	scalar	*Visual	NONE	NONE	NONE	NONE
Debris	scalar	*Visual	NONE	▲ MODER	VLITE	NONE
Sand/Dirt	scalar	*Visual	NONE	NONE	NONE	NONE
Appearance	scalar	*Visual	NORML	NORML	NORML	NORML
Odor	scalar	*Visual	NORML	NORML	NORML	NORML
Emulsified Water	scalar	*Visual	>0.2	NEG	NEG	NEG
Free Water	scalar	*Visual		NEG	ation BOLL FER	DIEBIEPEDALI




#### **OIL ANALYSIS REPORT**










### **GRAPHS**













Certificate L2367

Laboratory Sample No. Lab Number **Unique Number** 

: WC0823777 : 05900104 : 10561460 Test Package : IND 2

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received : 17 Jul 2023 Diagnosed : 18 Jul 2023 Diagnostician : Angela Borella

**LEPRINO FOODS - ALLENDALE** 

4700 RICH STREET ALLENDALE, MI US 49401

Contact: BILL FERRIER BFERRIER@LEPRINOFOODS.COM

To discuss this sample report, contact Customer Service at 1-800-237-1369. \* - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

T:

F: