

OIL ANALYSIS REPORT

Sample Rating Trend





DIAGNOSIS

Component

Recommendation

Hydraulic System

Oil and filter change at the time of sampling has been noted. We recommend an early resample to monitor this condition.

MARINE BULL - OLD

PETRO CANADA 10W (--- GAL)

The copper level is severe.

Contamination

There is no indication of any contamination in the oil.


Fluid Condition

The condition of the oil is acceptable for the time in service.

				Jun2023		
SAMPLE INFORI	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		WC0822342		
Sample Date		Client Info		29 Jun 2023		
Machine Age	hrs	Client Info		2409		
Oil Age	hrs	Client Info		270		
Oil Changed		Client Info		Changed		
Sample Status				SEVERE		
WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>20	10		
Chromium	ppm	ASTM D5185m	>10	0		
Nickel	ppm	ASTM D5185m	>10	0		
Titanium	ppm	ASTM D5185m		0		
Silver	ppm	ASTM D5185m		0		
Aluminum	ppm	ASTM D5185m	>10	<1		
Lead	ppm	ASTM D5185m	>10	<1		
Copper	ppm	ASTM D5185m	>75	921		
Tin	ppm	ASTM D5185m	>10	<1		
Vanadium	ppm	ASTM D5185m		0		
Cadmium	ppm	ASTM D5185m		0		
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m		72		
Barium	ppm	ASTM D5185m		0		
Molybdenum	ppm	ASTM D5185m		4		
Manganese	ppm	ASTM D5185m		<1		
Magnesium	ppm	ASTM D5185m		27		
Calcium	ppm	ASTM D5185m		2544		
Phosphorus	ppm	ASTM D5185m		916		
Zinc	ppm	ASTM D5185m		1070		
Sulfur	ppm	ASTM D5185m		3083		
CONTAMINANTS	3	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>20	10		
Sodium	ppm	ASTM D5185m		5		
Potassium	ppm	ASTM D5185m	>20	1		
VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	*Visual	NONE	NONE		
Yellow Metal	scalar	*Visual	NONE	NONE		
Precipitate	scalar	*Visual	NONE	NONE		
Silt	scalar	*Visual	NONE	NONE		
Debris	scalar	*Visual	NONE	NONE		
Sand/Dirt	scalar	*Visual	NONE	NONE		
Appearance	scalar	*Visual	NORML	NORML		
Odor	scalar	*Visual	NORML	NORML		
Emulsified Water	scalar	*Visual	>0.1	NEG		
Free Water	scalar	*Visual		NEG		
FLUID PROPER	ΓIES	method	limit/base	current	history1	history2



OIL ANALYSIS REPORT







Laboratory Sample No. Lab Number Unique Number : 10562239

: WC0822342 : 05900883

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received : 17 Jul 2023 Diagnosed

: 20 Jul 2023 Diagnostician : Jonathan Hester

Test Package : MOB 1 Certificate L2367 To discuss this sample report, contact Customer Service at 1-800-237-1369.

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

C.L. BENTON & SONS INC

706 38TH AVE N MYRTLE BEACH, SC US 29577

Contact: NEIL neil@clbenton.com

T:

F: Contact/Location: NEIL ? - CLBMYR