


OIL ANALYSIS REPORT

RIG 6 **R6-G-03 NKL**

Diesel Engine

NOT GIVEN (--- GAL)





Recommendation

Resample at the next service interval to monitor.

All component wear rates are normal.

Contamination

The amount and size of particulates present in the system are acceptable. There is no indication of any contamination in the oil.

Fluid Condition

The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is suitable for further service.

SAMPLE INFORM	MOITA	method	limit/base	current	history1	history2
Sample Number		Client Info		KL0012524	KL0011827	KL0009993
Sample Date		Client Info		24 Jun 2023	14 Apr 2023	15 Mar 2023
Machine Age	days	Client Info		45099	45025	44995
Oil Age	days	Client Info		0	0	0
Oil Changed		Client Info		N/A	N/A	N/A
Sample Status				NORMAL	ABNORMAL	NORMAL
CONTAMINATION	١	method	limit/base	current	history1	history2
Fuel		WC Method	>5	<1.0	<1.0	<1.0
Glycol		WC Method		NEG	NEG	NEG
WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>100	3	4	6
Chromium	ppm	ASTM D5185m	>20	<1	0	0
Nickel	ppm	ASTM D5185m	>4	0	0	0
Titanium	ppm	ASTM D5185m		0	0	0
Silver	ppm	ASTM D5185m	>3	0	0	<1
Aluminum	ppm	ASTM D5185m	>20	3	2	2
Lead	ppm	ASTM D5185m	>40	<1	0	0
Copper	ppm	ASTM D5185m	>330	<1	0	1
Tin	ppm	ASTM D5185m	>15	<1	0	0
Vanadium	ppm	ASTM D5185m		0	0	0
Cadmium	ppm	ASTM D5185m		0	0	0
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m		433	344	317
Barium	ppm	ASTM D5185m		0	0	0
Molybdenum	ppm	ASTM D5185m		130	126	134
Manganese	ppm	ASTM D5185m		<1	<1	<1
Magnesium	ppm	ASTM D5185m		727	654	726
Calcium	ppm	ASTM D5185m		1633	1459	1659
Phosphorus	ppm	ASTM D5185m		729	681	744
Zinc	ppm	ASTM D5185m		870	803	892
Sulfur	ppm	ASTM D5185m		3102	2558	3076
CONTAMINANTS		method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>25	8	△ 31	5
Sodium	ppm	ASTM D5185m		2	5	14
Potassium	ppm	ASTM D5185m	>20	3	0	0
INFRA-RED		method	limit/base	current	history1	history2
Soot %	%	*ASTM D7844	>3	0.1	0.1	0.2
Nitration	Abs/cm	*ASTM D7624	>20	4.8	7.3	9.0
Sulfation	Abs/.1mm	*ASTM D7415	>30	22.8	23.2	24.2




OIL ANALYSIS REPORT

cSt

Visc @ 100°C

ASTM D445



FLUID CLEANLINESS	method				history2
Particles >4µm	ASTM D7647	>20000	1810	1531	6473
Particles >6µm	ASTM D7647	>5000	986	834	3526
Particles >14μm	ASTM D7647	>640	168	142	600
Particles >21μm	ASTM D7647	>160	57	48	202
Particles >38μm	ASTM D7647	>40	9	7	31
Particles >71μm	ASTM D7647	>10	1	1	3
Oil Cleanliness	ISO 4406 (c)	>21/19/16	18/17/15	17/14	19/16
FLUID DECDADATION		11		Internation	la la tarre O


	se Nu	mber							
12.0									
5 10.0			_	1	~				/
8.0 0.0 0.0 0.0 0.0 0.0 0.0 0.0 0.0 0.0	//			1		\/	${\hspace{-0.1cm}{\checkmark}\hspace{-0.1cm}}$	\sim	
BW.		\/		1	/	i I			
a 6.0		V							
2 4.0									
2.0									
0.0	21-	21-	22	22	22	22	23	23	23
Nov4/21	Apr12/21	Dec8/	Feb11/	Apr29/2	Jul20/	0ct7/	Jan7/23	Mar15/2	Jun24/23
2	Ä		20	Ap	5	0	\neg	Š	3

FLUID DEGRADATION		memod			HISTOLAL	HISTORYZ	
	Oxidation	Abs/.1mm	*ASTM D7414	>25	15.9	17.3	19.5
	Base Number (BN)	mg KOH/g	ASTM D2896		11.13	9.69	9.16

Viscosity	y @ 1	00°C						
Abnormal				Λ				
Abnormal		_	\	/ \	سا	~	~	
Nov4/20	Dec8/21	eb11/22	Apr29/22	0/22	0ct7/22	Jan7/23	Mar15/23 -	

VISUAL		method	limit/base	current	history1	history2	
White Metal	scalar	*Visual	NONE	NONE	NONE	NONE	
Yellow Metal	scalar	*Visual	NONE	NONE	NONE	NONE	
Precipitate	scalar	*Visual	NONE	NONE	NONE	NONE	
Silt	scalar	*Visual	NONE	NONE	NONE	NONE	
Debris	scalar	*Visual	NONE	NONE	NONE	NONE	
Sand/Dirt	scalar	*Visual	NONE	NONE	NONE	NONE	
Appearance	scalar	*Visual	NORML	NORML	NORML	NORML	
Odor	scalar	*Visual	NORML	NORML	NORML	NORML	
Emulsified Water	scalar	*Visual	>0.2	NEG	NEG	NEG	
Free Water	scalar	*Visual		NEG	NEG	NEG	
FILLID DDODED	FIFO		11 11 //		111	1:	
FLUID PROPERT	ΠES	method				history2	

14.4



	GRAPE	15																
10	Ferrous	Alloys	3	-,						491,520 T	article	Cour	nt					т26
20	i	iron chromium			1	\				_	vere							+24
mdd 5		nickel		_	1	1	\wedge	/	_	30,720 AL	normal	1						-22
0	20	21		- 22		22	. 53	23	23	₹ 7,680	1		1					20 80
	Nov4/20 Apr12/21	Dec8/21	Feb11/22	Apr29/22	Jul20/22	Oct7/22	Jan7/23	Mar15/23	Jun24/23	7,680 1,920 1,920 480 480	_	1						+20 4406:1999 Cleanliness Code +18 +14 +14 +12
	Non-fer	rous N	1etal	s						480		1						16 Clea
10		copper								120 -			-	\				14 mliness
mdd 5	t									国 30-						\		-12 cd
0		25		-			_			8-							/	-10
	Nov4/20 -	Dec8/21	Feb11/22	Apr29/22	Jul20/22	Oct7/22	Jan7/23	Mar15/23	Jun24/23	2-								18
	≥ ₹ Viscosit				3	0	7	Ma	η	0 4µ		6 _µ	14μ		21μ	3	8µ	71 _µ
25		у (ш. т	JU-C							_В ,го Е	Base N	umbe	r					
					1					KOH KOH								
() 20 20 35 15	Abnormal		44		Α	-	Li	 		uper (m	$\overline{}$	V		-		~	\checkmark	
10				1	<u> </u>		_			Base Number (mg KOH/g)								
. 0	1/20	8/21	/22	3/22)/22	1/22	1/23	5/23	1/23	Ba	2/21	8/21	/22	3/22)/22	1/22	1/23	5/23





Laboratory Sample No. Lab Number

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 : KL0012524 : 05902884

Unique Number : 10564240

Received : 19 Jul 2023 Diagnosed

: 21 Jul 2023 Diagnostician : Don Baldridge

Test Package : MOB 2 (Additional Tests: PrtCount) To discuss this sample report, contact Customer Service at 1-800-237-1369.

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012) CITADEL DRILLING

7550 W I20 ODESSA, TX US 79763

Contact: MIKE COMBDEN mcombden@citadeldrilling.com

T: (780)955-5509

13.6

13.3

F: