

PROBLEM SUMMARY

PRODUCTION FLOOR [14857-SA] Machine Id SA1102 - EXTRUDER 2 (S/N E-3978)

Gear Extruder

MOBIL MOBILGEAR 632 (10 GAL)



Sample Rating Trend



COMPONENT CONDITION SUMMARY

No relevant graphs to display

RECOMMENDATION

Resample at the next service interval to monitor.

PROBLEMATIC T	EST RE	SULTS					
Sample Status				ABNORMAL	NORMAL	NORMAL	
Debris	scalar	*Visual	NONE	▲ MODER	VLITE	LIGHT	

Customer Id: MANSAN Sample No.: WC0837978 Lab Number: 05904494 Test Package: IND 2



To manage this report scan the QR code

To discuss the diagnosis or test data: Angela Borella +1 800-237-1369 angela.borella@wearcheckusa.com

To change component or sample information: Customer Service +1 1-800-237-1369 customerservice@wearcheck.com

RECOMMENDED ACTIONS

There are no recommended actions for this sample.

HISTORICAL DIAGNOSIS

26 Jul 2021 Diag: Wes Davis

NORMAL



Resample at the next service interval to monitor. The fluid was not specified, however, a fluid match indicates that this fluid is (GENERIC) GEAR OIL ISO 150. Please confirm.

All component wear rates are normal. There is no indication of any contamination in the oil. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.



16 Jul 2018 Diag: Wes Davis

NORMAL



Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.

View report

19 Jun 2017 Diag: Jonathan Hester

VISCOSITY



No corrective action is recommended at this time. Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the component. Viscosity of sample indicates oil is within ISO 150 range, advise investigate. Confirm oil type. The AN level is acceptable for this fluid.





OIL ANALYSIS REPORT


OIL ANAL 1313 REPOR

PRODUCTION FLOOR [14857-SA] Machine Id SA1102 - EXTRUDER 2 (S/N E-3978)

Component

Gear Extruder

MOBIL MOBILGEAR 632 (10 GAL)





DIAGNOSIS

Recommendation

Resample at the next service interval to monitor.

Wear

All component wear rates are normal.

Contamination

Moderate concentration of visible dirt/debris present in the oil.


Fluid Condition


The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.

SAMPLE INFORM	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		WC0837978	WC0600969	WCI2324645
Sample Date		Client Info		14 Jul 2023	26 Jul 2021	16 Jul 2018
Machine Age	yrs	Client Info		0	0	0
Oil Age	yrs	Client Info		0	0	0
Oil Changed	,	Client Info		N/A	Not Changd	Not Changd
Sample Status				ABNORMAL	NORMAL	NORMAL
WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>150	16	10	20
Chromium	ppm	ASTM D5185m	>10	0	0	0
Nickel	ppm	ASTM D5185m	>10	0	0	0
Titanium	ppm	ASTM D5185m		0	0	0
Silver	ppm	ASTM D5185m		0	<1	0
Aluminum	ppm	ASTM D5185m	>25	0	0	<1
Lead	ppm	ASTM D5185m	>100	<1	<1	0
Copper	ppm	ASTM D5185m	>50	<1	1	14
Tin	ppm		>10	0	<1	0
Antimony	ppm	ASTM D5185m	>5		0	0
Vanadium	ppm	ASTM D5185m		0	0	0
Cadmium	ppm	ASTM D5185m		0	0	0
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m		6	17	3
Barium	ppm	ASTM D5185m		2	0	0
Molybdenum	ppm	ASTM D5185m		1	1	0
Manganese	ppm	ASTM D5185m		<1	<1	<1
Magnesium	ppm	ASTM D5185m		<1	0	<1
Calcium	ppm	ASTM D5185m		5	4	0
Phosphorus	ppm	ASTM D5185m		319	332	162
Zinc	ppm	ASTM D5185m		7	1	45
Sulfur	ppm	ASTM D5185m		16264	13912	10092
CONTAMINANTS	;	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>50	<1	0	2
Sodium	ppm	ASTM D5185m		0	1	3
Potassium	ppm	ASTM D5185m	>20	<1	0	<1
FLUID DEGRADA	NOITA	method	limit/base	current	history1	history2
Acid Number (AN)	mg KOH/g	ASTM D8045		0.77	0.837	0.709
VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Yellow Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Precipitate	scalar	*Visual	NONE	NONE	NONE	NONE
Silt	scalar	*Visual	NONE	NONE	NONE	NONE
Debris	scalar	*Visual	NONE	▲ MODER	VLITE	LIGHT
Sand/Dirt	scalar	*Visual	NONE	NONE	NONE	NONE
Appearance	scalar	*Visual	NORML	NORML	NORML	NORML
Odor	scalar	*Visual	NORML	NORML	NORML	NORML
Emulsified Water	scalar	*Visual	>0.1	NEG	NEG	NEG
Free Water	scalar	*Visual		NEG	NRIQUE MCGF	RAWN M ANSA




OIL ANALYSIS REPORT







GRAPHS



Non-ferrous Metals









Certificate L2367

Laboratory Sample No.

Lab Number Unique Number : 10565850 Test Package : IND 2

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 : WC0837978 : 05904494

Received Diagnosed Diagnostician : Angela Borella

: 21 Jul 2023 : 25 Jul 2023

SAN ANTONIO, TX US 78219 Contact: ENRIQUE MCGRAW

MANTALINE CORPORATION

emcgraw@mantaline.com T: (210)243-8185

4267 DIVIDEND DR

To discuss this sample report, contact Customer Service at 1-800-237-1369.

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

F: (210)272-0436