

FILTER DEBRIS ANALYSIS

Sample Rating Trend







Machine Id FILTER 1 Component Filter Filuid NOT GIVEN (--- GAL)

DIAGNOSIS

Recommendation

Resample at the next service interval to monitor. Diagnostician's Note: The filters simply have a high amount of dirt and fibres and some non-ferrous wear debris. All normal. Our technician's did a spot toluene test on the filter patch to determine if the base material on the patch was varnish (insoluble). The test was negative indicating this is simply fine dirt, not varnish. All tests and evaluation performed at performed at WearCheck Canada.

Wear Particles

The filter contained no appreciable wear particles. All filter wear levels are normal.

Contaminants

The filter contained only normal levels of contaminants, and debris. All filter contaminant levels are normal.

SAMPLE INFORM	IATION	method	limit/base	current	history1	history2
Sample Number		Client Info		WC05904725		
Sample Date		Client Info		20 Jul 2023		
Machine Age	hrs	Client Info		0		
Oil Age	hrs	Client Info		0		
Oil Changed		Client Info		N/A		
Sample Status				NORMAL		
FILTER WEAR PAR	RTICLES	method	limit/base	current	history1	history2
Ferrous Rubbing	Scale 0-10	*ASTM D7684		1		
Ferrous Sliding	Scale 0-10	*ASTM D7684				
Ferrous Cutting	Scale 0-10	*ASTM D7684				
Ferrous Rolling	Scale 0-10	*ASTM D7684				
Ferrous Break-in	Scale 0-10	*ASTM D7684				
Ferrous Spheres	Scale 0-10	*ASTM D7684				
Ferrous Black Oxides	Scale 0-10	*ASTM D7684				
Ferrous Red Oxides	Scale 0-10	*ASTM D7684				
Ferrous Corrosive	Scale 0-10	*ASTM D7684				
Ferrous Other	Scale 0-10	*ASTM D7684				
Nonferrous Rubbing	Scale 0-10	*ASTM D7684		1		
Nonferrous Sliding	Scale 0-10	*ASTM D7684		1		
Nonferrous Cutting	Scale 0-10	*ASTM D7684				
Nonferrous Rolling	Scale 0-10	*ASTM D7684		1		
Nonferrous Other	Scale 0-10	*ASTM D7684				
FILTER CONTAM	INANTS	method	limit/base	current	history1	history2
Sand/Dirt	Scale 0-10	ASTM D7684		5		
Fibres	Scale 0-10	*ASTM D7684		4		
Spheres	Scale 0-10	*ASTM D7684				
Other	Scale 0-10	*ASTM D7684				
Patch Weight	mg	*ASTM D7684		100		
SAMPLE IMAGES	5	method	limit/base	current	history1	history2
Color				no image	no image	no image
Bottom				no image	no image	no image



FILTER REPORT

Machine Id FILTER 1 Component Filter Fluid NOT GIVEN (--- GAL)



Magn: 60x Illum: RW



WEAR

The filter contained no appreciable wear particles. All filter wear levels are normal.