

PROBLEM SUMMARY

Sample Rating Trend

WEAR




AREA II [500298287] Machine Id CHEMINEER A8003 (S/N AD-30-7) Component

Gearbox

ROYAL PURPLE SYNFILM GT 220 (7 GAL)

COMPONENT CONDITION SUMMARY



RECOMMENDATION

No corrective action is recommended at this time. Resample at the next service interval to monitor.

PROBLEMATIC T	DBLEMATIC TEST RESULTS							
Sample Status				ABNORMAL	ABNORMAL	ABNORMAL		
Aluminum	ppm	ASTM D5185m	>25	4 0	4 3	4 1		

Customer Id: ALBORA Sample No.: WC0810171 Lab Number: 05904994 Test Package: IND 2



To manage this report scan the QR code

To discuss the diagnosis or test data:

Don Baldridge +1 don.b505@comcast.net

To change component or sample information: Customer Service +1 1-800-237-1369 customerservice@wearcheck.com

RECOMMENDED ACTIONS

There are no recommended actions for this sample.

HISTORICAL DIAGNOSIS

15 Mar 2023 Diag: Don Baldridge

WEAR



No corrective action is recommended at this time. We recommend an early resample to monitor this condition. The aluminum level is abnormal. All other component wear rates are normal. There is no indication of any contamination in the oil. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.



13 Dec 2022 Diag: Don Baldridge

WEAR



No corrective action is recommended at this time. We recommend an early resample to monitor this condition. The aluminum level is abnormal. All other component wear rates are normal. There is no indication of any contamination in the oil. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.



13 Sep 2022 Diag: Doug Bogart

VISCOSITY



Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The amount and size of particulates present in the system are acceptable. Viscosity of sample indicates oil is within ISO 150 range, advise investigate. Confirm oil type. The AN level is acceptable for this fluid.






OIL ANALYSIS REPORT

AREA II [500298287] CHEMINEER A8003 (S/N AD-30-7)

Gearbox

ROYAL PURPLE SYNFILM GT 220 (7 GAL)





DIAGNOSIS

Recommendation

No corrective action is recommended at this time. Resample at the next service interval to monitor.

The aluminum level is abnormal. All other component wear rates are normal.

Contamination

There is no indication of any contamination in the


Fluid Condition

The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.


			1 Jun2012 Nov2012 Nov20			
SAMPLE INFORM	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		WC0810171	WC0780987	WC0758486
Sample Date		Client Info		05 Jun 2023	15 Mar 2023	13 Dec 2022
Machine Age	hrs	Client Info		0	0	0
Oil Age	hrs	Client Info		0	0	0
Oil Changed		Client Info		N/A	N/A	N/A
Sample Status				ABNORMAL	ABNORMAL	ABNORMAL
WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>200	6	7	7
Chromium	ppm	ASTM D5185m	>15	0	0	0
Nickel	ppm	ASTM D5185m	>15	0	<1	0
Titanium	ppm	ASTM D5185m		0	0	0
Silver	ppm	ASTM D5185m		0	0	0
Aluminum	ppm	ASTM D5185m	>25	40	4 3	<u> 41</u>
Lead	ppm	ASTM D5185m	>100	0	0	0
Copper	ppm		>200	0	0	0
Tin	ppm	ASTM D5185m	>25	0	0	0
Vanadium	ppm	ASTM D5185m	2.20	0	0	0
Cadmium	ppm	ASTM D5185m		0	0	0
	ррііі		11 11 11			
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m		0	0	0
Barium	ppm	ASTM D5185m		<1	0	0
Molybdenum	ppm	ASTM D5185m		2	2	1
Manganese	ppm	ASTM D5185m		0	<1	<1
Magnesium	ppm	ASTM D5185m		43	73	72
Calcium	ppm	ASTM D5185m		0	2	2
Phosphorus	ppm	ASTM D5185m		10	17	14
Zinc	ppm	ASTM D5185m		33	36	31
Sulfur	ppm	ASTM D5185m		22039	24800	22424
CONTAMINANTS		method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>50	2	4	4
Sodium	ppm	ASTM D5185m		0	1	<1
Potassium	ppm	ASTM D5185m	>20	1	<1	0
FLUID DEGRADA	TION	method	limit/base	current	history1	history2
Acid Number (AN)	mg KOH/g	ASTM D8045		0.43	0.41	0.52
VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	*Visual	NONE	NONE	LIGHT	NONE
Yellow Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Precipitate	scalar	*Visual	NONE	NONE	NONE	NONE
Silt	scalar	*Visual	NONE	NONE	NONE	NONE
Debris	scalar	*Visual	NONE	LIGHT	NONE	NONE
Sand/Dirt	scalar	*Visual	NONE	NONE	NONE	NONE
Appearance	scalar	*Visual	NORML	NORML	NORML	NORML
Odor	scalar	*Visual	NORML	NORML	NORML	NORML
Emulsified Water	scalar	*Visual	>0.2	NEG	NEG	NEG
Free Water	scalar	*Visual		NEG	NEG	NEG




OIL ANALYSIS REPORT













GRAPHS













Certificate L2367

Laboratory Sample No. Lab Number **Unique Number** Test Package : IND 2

: WC0810171 : 05904994 : 10566350

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received : 21 Jul 2023 Diagnosed : 25 Jul 2023 : Don Baldridge Diagnostician

SI GROUP INC - ALBEMARLE 725 CANNON BRIDGE RD ORANGEBURG, SC

US 29115

F: (803)539-5426

Contact: ERIC PROVEAUX

eric.proveaux@contractors.siigroup.com T: (803)539-5228

To discuss this sample report, contact Customer Service at 1-800-237-1369.

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

Report Id: ALBORA [WUSCAR] 05904994 (Generated: 07/25/2023 11:53:58) Rev: 1

Submitted By: KIRK WILLIAMS