



# FUEL REPORT

Sample Rating Trend

**NORMAL**



Machine Id  
**NISSAN 24820-03**

Component  
**Gasoline**

Fluid  
**GASOLINE (--- GAL)**

## DIAGNOSIS

### Recommendation

No corrective action is recommended at this time.

### Wear

{not applicable}

### Contamination

Anthrone test for sugar contamination is negative.  
The water content is negligible.

### Fluid Condition

{not applicable}

## SAMPLE INFORMATION

	method	limit/base	current	history1	history2
Sample Number	Client Info		<b>WCM2007240</b>	---	---
Sample Date	Client Info		<b>10 Aug 2023</b>	---	---
Machine Age	mls	Client Info	<b>0</b>	---	---
Oil Age	mls	Client Info	<b>0</b>	---	---
Oil Changed		Client Info	<b>N/A</b>	---	---
Sample Status			<b>NORMAL</b>	---	---


## CONTAMINANTS

	method	limit/base	current	history1	history2
Water	%	ASTM D6304 <0.05	<b>0.010</b>	---	---
ppm Water	ppm	ASTM D6304 <500	<b>100.7</b>	---	---


## SAMPLE IMAGES

	method	limit/base	current	history1	history2
Color				no image	no image
Bottom				no image	no image

# FUEL REPORT



## GRAPHS



Certificate L2367

**Laboratory** : WearCheck USA - 501 Madison Ave., Cary, NC 27513  
**Sample No.** : WCM2007240     **Received** : 11 Aug 2023  
**Lab Number** : 05922618     **Diagnosed** : 18 Aug 2023  
**Unique Number** : 10602565     **Diagnostician** : Doug Bogart  
**Test Package** : MOB 2 ( Additional Tests: KF, SUGAR )

**SOUTHERN AUTOMOTIVE CONSULTING**  
 P.O. BOX 730  
 CREEDMOOR, NC  
 US 27522  
 Contact: ANDREW MORTON  
 andymorton711@yahoo.com  
 T:  
 F:

To discuss this sample report, contact Customer Service at 1-800-237-1369.  
 \* - Denotes test methods that are outside of the ISO 17025 scope of accreditation.  
 Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)