


PROBLEM SUMMARY

Recovery Machine Id Pro Quip FFI56BB01 Standardization Tank, Agitator

Gearbox

JAX MAGNA-PLATE 460 FG (--- GAL)

COMPONENT CONDITION SUMMARY



RECOMMENDATION

No corrective action is recommended at this time. Resample at the next service interval to monitor.

AL AL	Ан			
	C TEST RESULTS			
Sample Status	TESTRESOLIS	ABNORMAL	ABNORMAL	ABNORMAL
Particles >4µm	ASTM D7647 >200	00 🔺 54139	A 77701	▲ 87444
Oil Cleanliness	ISO 4406 (c) >21/1	9/16 🔺 23/18/13	▲ 23/18/12	4 /19/13


Customer Id: NOVFRANC Sample No.: WC0835755 Lab Number: 05923438 Test Package: IND 2



To manage this report scan the QR code

To discuss the diagnosis or test data: Don Baldridge +1 <u>don.b505@comcast.net</u>

To change component or sample information: Customer Service +1 1-800-237-1369 <u>customerservice@wearcheck.com</u>



RECOMMENDED ACTIONS

There are no recommended actions for this sample.

HISTORICAL DIAGNOSIS

10 Aug 2022 Diag: Doug Bogart



No corrective action is recommended at this time. Resample at the next service interval to monitor.All component wear rates are normal. There is a high amount of silt (particulates < 6 microns in size) present in the oil. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.



25 Aug 2021 Diag: Jonathan Hester



No corrective action is recommended at this time. Resample at the next service interval to monitor.All component wear rates are normal. There is a high amount of silt (particulates < 6 microns in size) present in the oil. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.





17 Aug 2021 Diag: Jonathan Hester

No corrective action is recommended at this time. Resample at the next service interval to monitor.All component wear rates are normal. There is a high amount of silt (particulates < 14 microns in size) present in the oil. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.





OIL ANALYSIS REPORT

Area Recovery Pro Quip FFI56BB01 Standardization Tank, Agitator Component

Gearbox

Fluid JAX MAGNA-PLATE 460 FG (--- GAL)

DIAGNOSIS

Recommendation

No corrective action is recommended at this time. Resample at the next service interval to monitor.

Wear


All component wear rates are normal.

Contamination

There is a high amount of silt (particulates < 14 microns in size) present in the oil.

Fluid Condition

The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.



SAMPLE INFORM	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		WC0835755	WC0725999	WC0611274
Sample Date		Client Info		11 Aug 2023	10 Aug 2022	25 Aug 2021
Machine Age	hrs	Client Info		0	0	0
Oil Age	hrs	Client Info		0	0	0
Oil Changed		Client Info		N/A	N/A	N/A
Sample Status				ABNORMAL	ABNORMAL	ABNORMAL
WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>200	8	8	7
Chromium	ppm	ASTM D5185m	>15	0	0	0
Nickel	ppm	ASTM D5185m	>15	0	0	0
Titanium	ppm	ASTM D5185m		<1	0	0
Silver	ppm	ASTM D5185m		0	0	0
Aluminum	ppm	ASTM D5185m	>25	<1	<1	0
Lead	ppm	ASTM D5185m		0	0	0
Copper	ppm	ASTM D5185m		<1	0	0
Tin	ppm	ASTM D5185m	>25	<1	0	0
Antimony	ppm	ASTM D5185m				0
Vanadium	ppm	ASTM D5185m		<1	0	0
Cadmium	ppm	ASTM D5185m		0	0	0
ADDITIVES		method	limit/base		history1	history2
			inititi base			
Boron	ppm	ASTM D5185m		0	0	1
Barium	ppm	ASTM D5185m		<1	2	0
Molybdenum	ppm	ASTM D5185m		0	0	0
Manganese	ppm	ASTM D5185m		<1	<1	0
Magnesium	ppm	ASTM D5185m		6	0	0
Calcium	ppm	ASTM D5185m		<1		0
Phosphorus	ppm	ASTM D5185m		556	555	579
Zinc	ppm	ASTM D5185m		17	<1	0
Sulfur	ppm	ASTM D5185m		633	532	642
CONTAMINANTS	6	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>50	2	2	1
Sodium	ppm	ASTM D5185m		1	<1	0
Potassium	ppm	ASTM D5185m		<1	0	0
Water	%	ASTM D6304		0.009	0.006	0.001
ppm Water	ppm	ASTM D6304	>2000	96.5	66.2	0.00
FLUID CLEANLIN	NESS	method	limit/base	current	history1	history2
Particles >4µm		ASTM D7647	>20000	4 54139	A 77701	▲ 87444
Particles >6µm		ASTM D7647	>5000	1902	1511	3531
Particles >14µm		ASTM D7647	>640	48	31	50
Particles >21µm		ASTM D7647	>160	13	6	9
Particles >38µm		ASTM D7647	>40	0	0	1
Particles >71µm		ASTM D7647	>10	0	0	0
Oil Cleanliness		ISO 4406 (c)	>21/19/16	A 23/18/13	▲ 23/18/12	▲ 24/19/13
FLUID DEGRADA	ATION	method	limit/base	current	history1	history2
Acid Number (AN)	mg KOH/g	ASTM D8045		0.74	0.78	0.697
0.57.28) Dov: 1					Submitted Dur	

Report Id: NOVFRANC [WUSCAR] 05923438 (Generated: 08/15/2023 12:57:38) Rev: 1

Submitted By: CHASE MCGEE



400 3501

300

£ 250

TE 200 150

100

50


1.20 0.9

0.24

0.80


0.70

OIL ANALYSIS REPORT





Bottom



Submitted By: CHASE MCGEE

Page 4 of 4