

# **OIL ANALYSIS REPORT**

#### Area OKLAHOMA/3/EG - TRUCK-OFF-HWY-HEAVY HAUL Machine Id 69.02 [OKLAHOMA^3^EG - TRUCK-OFF-HWY-HEAVY HAUL] Component Rear Right Final Drive

Sample Rating Trend



NORMAL

Fluid MOBIL 50W (--- GAL)

### DIAGNOSIS

#### Recommendation

Resample at the next service interval to monitor.

#### Wear

All component wear rates are normal.

#### Contamination

The water content is negligible. There is no indication of any contamination in the oil.


### Fluid Condition

The condition of the oil is acceptable for the time in service.

SAMPLE INFORM	IATION	method	limit/base	current	history1	history2
Sample Number		Client Info		WC0834071	WC0778283	WC0758751
Sample Date		Client Info		05 Aug 2023	28 Feb 2023	04 Nov 2022
Machine Age	hrs	Client Info		22584	21769	21084
Oil Age	hrs	Client Info		21084	61668	1000
Oil Changed		Client Info		N/A	N/A	Changed
Sample Status				NORMAL	ABNORMAL	NORMAL
WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>800	12	11	15
Chromium	ppm	ASTM D5185m	>10	<1	<1	0
Nickel	ppm	ASTM D5185m	>5	<1	<1	0
Titanium	ppm	ASTM D5185m	>15	<1	<1	0
Silver	ppm	ASTM D5185m	>2	0	0	0
Aluminum	ppm	ASTM D5185m	>75	2	2	0
Lead	ppm	ASTM D5185m	>10	<1	0	<1
Copper	ppm	ASTM D5185m	>75	2	1	4
Tin	ppm	ASTM D5185m	>8	_ <1	0	<1
Antimony	ppm	ASTM D5185m	>50			
Vanadium	ppm	ASTM D5185m		0	0	0
Cadmium	ppm	ASTM D5185m		0	0	0
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m		12	12	11
Barium	ppm	ASTM D5185m		2	0	0
Molybdenum	ppm	ASTM D5185m		3	3	<1
Manganese	ppm	ASTM D5185m		0	<1	0
Magnesium	ppm	ASTM D5185m		27	30	7
Calcium	ppm	ASTM D5185m		2875	2840	1063
Phosphorus	ppm	ASTM D5185m		1008	979	636
Zinc	ppm	ASTM D5185m		1181	1155	427
Sulfur	ppm	ASTM D5185m		9353	9048	3023
CONTAMINANTS	le le	method	limit/base	current	history1	history2
Silicon	0000	ASTM D5185m		10	9	21
Sodium	ppm	ASTM D5185m	>400	0	5	0
Potassium	ppm	ASTM D5185m	× 20	1	5 <1	2
	ppm	ASTIVI DOTIODITI	>20	1	< 1	2
VISUAL		in a la sul su sul su sul su sul su sul su sul su	line it //		late to set	biston C
Maite Met-1		method	limit/base	current	history1	history2
White Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Yellow Metal	scalar	*Visual *Visual	NONE NONE	NONE NONE	NONE NONE	NONE NONE
Yellow Metal Precipitate	scalar scalar	*Visual *Visual *Visual	NONE NONE NONE	NONE NONE NONE	NONE NONE NONE	NONE NONE NONE
Yellow Metal Precipitate Silt	scalar scalar scalar	*Visual *Visual *Visual *Visual	NONE NONE NONE	NONE NONE NONE NONE	NONE NONE NONE NONE	NONE NONE NONE NONE
Yellow Metal Precipitate Silt Debris	scalar scalar scalar scalar	*Visual *Visual *Visual *Visual *Visual	NONE NONE NONE NONE	NONE NONE NONE NONE NONE	NONE NONE NONE NONE	NONE NONE NONE NONE
Yellow Metal Precipitate Silt Debris Sand/Dirt	scalar scalar scalar scalar scalar	*Visual *Visual *Visual *Visual *Visual *Visual	NONE NONE NONE NONE NONE	NONE NONE NONE NONE NONE NONE	NONE NONE NONE NONE NONE	NONE NONE NONE NONE NONE
Yellow Metal Precipitate Silt Debris Sand/Dirt Appearance	scalar scalar scalar scalar scalar scalar	*Visual *Visual *Visual *Visual *Visual *Visual	NONE NONE NONE NONE NONE NORE	NONE NONE NONE NONE NONE NORE	NONE NONE NONE NONE NONE NORML	NONE NONE NONE NONE NONE NORML
Yellow Metal Precipitate Silt Debris Sand/Dirt Appearance Odor	scalar scalar scalar scalar scalar scalar scalar	*Visual *Visual *Visual *Visual *Visual *Visual *Visual	NONE NONE NONE NONE NONE NORML NORML	NONE NONE NONE NONE NONE NORML NORML	NONE NONE NONE NONE NONE NORML NORML	NONE NONE NONE NONE NONE NORML NORML
Yellow Metal Precipitate Silt Debris Sand/Dirt Appearance	scalar scalar scalar scalar scalar scalar	*Visual *Visual *Visual *Visual *Visual *Visual	NONE NONE NONE NONE NONE NORE	NONE NONE NONE NONE NONE NORE	NONE NONE NONE NONE NONE NORML	NONE NONE NONE NONE NONE NORML




## **OIL ANALYSIS REPORT**




FLUID PROPERTIES		method	limit/base	current	history1	history2
Visc @ 40°C	cSt	ASTM D445		176	178	142
SAMPLE IMAGES		method	limit/base	current	history1	history2
Color				no image	no image	no image
Bottom				no image	no image	no image





SHERWOOD CONSTRUCTION CO INC 3219 WEST MAY ST WICHITA, KS US 67213 Contact: DOUG KING doug.king@sherwood.net T: (316)617-3161 F: x:





Test Package : CONST Certificate L2367 To discuss this sample report, contact Customer Service at 1-800-237-1369. \* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

Received

Diagnosed

: 14 Aug 2023

: 15 Aug 2023

Diagnostician : Don Baldridge

: WC0834071

: 05923719

Submitted By: GARRETT ADAMS

Page 2 of 2