


OIL ANALYSIS REPORT



OKLAHOMA/3/EG - EXCAVATOR 20.69L [OKLAHOMA^3^EG - EXCAVATOR]

Component Left Swing Drive

MOBIL DELVAC 1350 (--- GAL)





DIAGNOSIS

Recommendation

Resample at the next service interval to monitor.

All component wear rates are normal.

Contamination

There is no indication of any contamination in the


Fluid Condition

The condition of the oil is acceptable for the time in service.


<u> </u>		0ctZ015	Aug2017 Nov2017	Jul2019 Feb2020 Di	ec2022	
SAMPLE INFORM	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		WC0834063	WC0758656	WC0578268
Sample Date		Client Info		05 Aug 2023	06 Dec 2022	09 Jun 2021
Machine Age	hrs	Client Info		12061	4973	2706
Oil Age	hrs	Client Info		4568	2590	1854
Oil Changed		Client Info		N/A	N/A	Changed
Sample Status				NORMAL	NORMAL	NORMAL
WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>400	38	45	40
Chromium	ppm	ASTM D5185m	>10	<1	<1	<1
Nickel	ppm	ASTM D5185m	>10	<1	<1	<1
Titanium	ppm	ASTM D5185m		<1	<1	<1
Silver	ppm	ASTM D5185m		2	0	0
Aluminum	ppm	ASTM D5185m	>25	3	5	1
Lead	ppm	ASTM D5185m	>50	0	2	<1
Copper	ppm	ASTM D5185m	>200	<1	<1	<1
Tin	ppm	ASTM D5185m	>10	0	<1	<1
Antimony	ppm	ASTM D5185m	>5			<1
Vanadium	ppm	ASTM D5185m		0	0	0
Cadmium	ppm	ASTM D5185m		<1	0	0
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m		13	11	24
Barium	ppm	ASTM D5185m		2	0	0
Molybdenum	ppm	ASTM D5185m		4	4	4
Manganese	ppm	ASTM D5185m		<1	<1	<1
Magnesium	ppm	ASTM D5185m		37	35	32
Calcium	ppm	ASTM D5185m		2989	3149	2856
Phosphorus	ppm	ASTM D5185m		1041	1037	1039
Zinc	ppm	ASTM D5185m		1237	1322	1225
Sulfur	ppm	ASTM D5185m		15633	15285	10826
CONTAMINANTS		method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>50	6	6	6
Sodium	ppm	ASTM D5185m		0	2	2
Potassium	ppm	ASTM D5185m	>20	2	1	<1
VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Yellow Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Precipitate	scalar	*Visual	NONE	NONE	NONE	NONE
Silt	scalar	*Visual	NONE	NONE	NONE	NONE
Debris	scalar	*Visual	NONE	NONE	NONE	NONE
Sand/Dirt	scalar	*Visual	NONE	NONE	NONE	NONE
Appearance	scalar	*Visual	NORML	NORML	NORML	NORML
Odor	scalar	*Visual	NORML	NORML	NORML	NORML
Emulsified Water	scalar	*Visual	>0.2	NEG	NEG	NEG
Free Water	scalar	*Visual		NEG	NEG	NEG





OIL ANALYSIS REPORT



FLUID PROPERTIES		method	limit/base	current	history1	history2
Visc @ 40°C	cSt	ASTM D445	208	186	188	185
SAMPLE IMAGES		method	limit/base	current	history1	history2
Color				no image	no image	no image
Bottom				no image	no image	no image











Laboratory Sample No. Lab Number

Unique Number : 10603708 Test Package : CONST

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 : WC0834063 : 05923761

Received Diagnosed Diagnostician : Don Baldridge

: 14 Aug 2023 : 15 Aug 2023 SHERWOOD CONSTRUCTION CO INC

3219 WEST MAY ST WICHITA, KS US 67213 Contact: DOUG KING doug.king@sherwood.net

T: (316)617-3161

To discuss this sample report, contact Customer Service at 1-800-237-1369.

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

Report Id: SHEWIC [WUSCAR] 05923761 (Generated: 08/15/2023 14:28:32) Rev: 1

Submitted By: GARRETT ADAMS

F: x: