

PROBLEM SUMMARY

KAESER SK 15 4731630 (S/N 1023)

Compressor

KAESER SIGMA (OEM) S-460 (--- GAL)

COMPONENT CONDITION SUMMARY



RECOMMENDATION

The filter change at the time of sampling has been noted. We were unable to perform a particle count due to a high concentration of particles present in this sample. We advise that you stop the unit and follow the water drain-off procedure for this component. We recommend an early resample in 500 hours to monitor this condition.

PROBLEMATIC TEST RESULTS Sample Status ABNORMAL **ATTENTION** ATTENTION Water % ASTM D6304 >0.05 0.244 0.005 0.015 ppm Water ASTM D6304 >500 2440 57.8 150 ppm NONE Silt scalar *Visual MODER NONE NONE Debris scalar *Visual NONE MODER NONE NONE scalar *Visual NORML HAZY NORML NORML Appearance **Emulsified Water** scalar *Visual >0.05 **0.2%** NEG NEG

Customer Id: URBSTL Sample No.: KCPA005950 Lab Number: 05924338 Test Package: IND 2



To manage this report scan the QR code

To discuss the diagnosis or test data: Don Baldridge +1 don.b505@comcast.net

To change component or sample information: Customer Service +1 1-800-237-1369 <u>customerservice@wearcheck.com</u>



| RECOMMEND | ED ACTIONS | | | |
|-----------|------------|------|---------|-----------|
| Action | Status | Date | Done By | Des |
| Alert | | | ? | We par |

Description

We were unable to perform a particle count due to a high concentration of particles present in this sample.

HISTORICAL DIAGNOSIS



29 Nov 2022 Diag: Don Baldridge

No corrective action is recommended at this time. Oil and filter change at the time of sampling has been noted. Resample at the next service interval to monitor.All component wear rates are normal. There is a moderate amount of particulates present in the oil. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.



12 Feb 2018 Diag: Jonathan Hester



The filter change at the time of sampling has been noted. Resample at the next service interval to monitor.All component wear rates are normal. There is a moderate amount of particulates present in the oil. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.





OIL ANALYSIS REPORT

Machine Id KAESER SK 15 4731630 (S/N 1023) Component

Compressor

KAESER SIGMA (OEM) S-460 (--- GAL)

DIAGNOSIS

Recommendation

The filter change at the time of sampling has been noted. We were unable to perform a particle count due to a high concentration of particles present in this sample. We advise that you stop the unit and follow the water drain-off procedure for this component. We recommend an early resample in 500 hours to monitor this condition.

Wear

All component wear rates are normal.

Contamination

Moderate concentration of visible dirt/debris present in the oil. There is a moderate amount of visible silt present in the sample. There is a light concentration of water present in the oil.

Fluid Condition

The AN level is acceptable for this fluid.



| SAMPLE INFORM | IATION | method | limit/base | current | history1 | history2 |
|------------------|---------------|--------------|------------|---------------|-------------|-------------|
| Sample Number | | Client Info | | KCPA005950 | KCP49877 | KCP03605 |
| Sample Date | | Client Info | | 08 Aug 2023 | 29 Nov 2022 | 12 Feb 2018 |
| Machine Age | hrs | Client Info | | 16987 | 13163 | 5331 |
| Oil Age | hrs | Client Info | | 0 | 5000 | 1534 |
| Oil Changed | | Client Info | | N/A | Changed | Not Changd |
| Sample Status | | | | ABNORMAL | ATTENTION | ATTENTION |
| WEAR METALS | | method | limit/base | current | history1 | history2 |
| Iron | ppm | ASTM D5185m | >50 | 0 | <1 | <1 |
| Chromium | ppm | ASTM D5185m | >10 | 0 | 0 | 0 |
| Nickel | ppm | ASTM D5185m | >3 | 0 | 0 | 0 |
| Titanium | ppm | ASTM D5185m | >3 | 0 | 0 | 0 |
| Silver | ppm | ASTM D5185m | >2 | 0 | 0 | 0 |
| Aluminum | ppm | ASTM D5185m | >10 | <1 | 0 | 0 |
| Lead | ppm | ASTM D5185m | >10 | 0 | 0 | 0 |
| Copper | ppm | ASTM D5185m | >50 | 8 | 27 | 4 |
| Tin | ppm | ASTM D5185m | >10 | 0 | 0 | <1 |
| Antimony | ppm | ASTM D5185m | | | | 0 |
| Vanadium | ppm | ASTM D5185m | | 0 | 0 | 0 |
| Cadmium | ppm | ASTM D5185m | | 0 | 0 | 0 |
| ADDITIVES | | method | limit/base | current | history1 | history2 |
| Boron | ppm | ASTM D5185m | | 0 | 0 | 0 |
| Barium | ppm | ASTM D5185m | 90 | 0 | 0 | 0 |
| Molybdenum | ppm | ASTM D5185m | | 0 | 0 | 0 |
| Manganese | ppm | ASTM D5185m | | <1 | 0 | <1 |
| Magnesium | ppm | ASTM D5185m | 90 | 16 | 3 | 44 |
| Calcium | ppm | ASTM D5185m | 2 | 0 | 0 | 0 |
| Phosphorus | ppm | ASTM D5185m | | 3 | 32 | 33 |
| Zinc | ppm | ASTM D5185m | | 16 | 49 | 6 |
| Sulfur | ppm | ASTM D5185m | | 16352 | 22835 | 17444 |
| CONTAMINANTS | | method | limit/base | current | history1 | history2 |
| Silicon | ppm | ASTM D5185m | >25 | 0 | <1 | 0 |
| Sodium | ppm | ASTM D5185m | | 2 | <1 | 18 |
| Potassium | ppm | ASTM D5185m | >20 | <1 | 0 | <1 |
| Water | % | ASTM D6304 | >0.05 | <u> </u> | 0.005 | 0.015 |
| ppm Water | ppm | ASTM D6304 | >500 | A 2440 | 57.8 | 150 |
| FLUID CLEANLIN | IESS | method | limit/base | current | history1 | history2 |
| Particles >4µm | | ASTM D7647 | | | 6629 | 4253 |
| Particles >6µm | | ASTM D7647 | >1300 | | <u> </u> | 1201 |
| Particles >14µm | | ASTM D7647 | >80 | | 1 31 | 1 09 |
| Particles >21µm | | ASTM D7647 | >20 | | <u> </u> | <u> </u> |
| Particles >38µm | | ASTM D7647 | >4 | | 0 | 2 |
| Particles >71µm | | ASTM D7647 | >3 | | 0 | 0 |
| Oil Cleanliness | | ISO 4406 (c) | >/17/13 | | ▲ 20/18/14 | ▲ 17/14 |
| FLUID DEGRADA | TION | method | limit/base | current | history1 | history2 |
| Acid Number (AN) | mg KOH/g | ASTM D8045 | 0.4 | 0.34 | 0.37 | 0.307 |

Report Id: URBSTL [WUSCAR] 05924338 (Generated: 08/16/2023 09:46:09) Rev: 1

Contact/Location: ? ? - URBSTL



Built for a lifetime

OIL ANALYSIS REPORT







| VISUAL | | method | limit/base | current | history1 | history2 |
|------------------|--------|-----------|------------|-------------|----------|----------|
| White Metal | scalar | *Visual | NONE | NONE | NONE | NONE |
| Yellow Metal | scalar | *Visual | NONE | NONE | NONE | NONE |
| Precipitate | scalar | *Visual | NONE | NONE | NONE | NONE |
| Silt | scalar | *Visual | NONE | A MODER | NONE | NONE |
| Debris | scalar | *Visual | NONE | A MODER | NONE | NONE |
| Sand/Dirt | scalar | *Visual | NONE | NONE | NONE | NONE |
| Appearance | scalar | *Visual | NORML | 🔺 HAZY | NORML | NORML |
| Odor | scalar | *Visual | NORML | NORML | NORML | NORML |
| Emulsified Water | scalar | *Visual | >0.05 | 6.2% | NEG | NEG |
| Free Water | scalar | *Visual | | NEG | NEG | NEG |
| FLUID PROPERT | IES | method | limit/base | current | history1 | history2 |
| Visc @ 40°C | cSt | ASTM D445 | 46 | 44.7 | 49.5 | 43.6 |
| SAMPLE IMAGES | 6 | method | limit/base | current | history1 | history2 |
| Color | | | | | | - |



Bottom





Certificate L2367

Contact/Location: ? ? - URBSTL

Page 4 of 4