

OIL ANALYSIS REPORT

EL SAUZ L01WEA90058 (S/N GME004427A-79)

Hydraulic System

SHELL TELLUS S2 VX 32 (500 LTR)

Sample Rating Trend



Recommendation

Resample at the next service interval to monitor.

All component wear rates are normal.

Contamination

There is no indication of any contamination in the oil. The amount and size of particulates present in the system are acceptable.

Fluid Condition

The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.

			ı	Aug2023		
SAMPLE INFORM	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		NX014527		
Sample Date		Client Info		03 Aug 2023		
Machine Age	hrs	Client Info		0		
Oil Age	hrs	Client Info		0		
Oil Changed		Client Info		N/A		
Sample Status				NORMAL		
WEAR METALS		method	limit/base	current	history1	history2
PQ		ASTM D8184		15		
Iron	ppm	ASTM D5185m	>20	0		
Chromium	ppm	ASTM D5185m	>20	0		
Nickel	ppm	ASTM D5185m	>20	0		
Titanium	ppm	ASTM D5185m		0		
Silver	ppm	ASTM D5185m		0		
Aluminum	ppm	ASTM D5185m	>20	<1		
Lead	ppm	ASTM D5185m	>20	<1		
Copper	ppm	ASTM D5185m	>20	<1		
Tin		ASTM D5185m	>20	0		
Vanadium	ppm		>20	0		
Cadmium	ppm	ASTM D5185m		0		
	ppm	ASTM D5185m		U		
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m		0		
Barium	ppm	ASTM D5185m		0		
Molybdenum	ppm	ASTM D5185m		0		
Manganese	ppm	ASTM D5185m		0		
Magnesium	ppm	ASTM D5185m		60		
Calcium	ppm	ASTM D5185m		10		
Phosphorus	ppm	ASTM D5185m		280		
Zinc	ppm	ASTM D5185m		317		
Sulfur	ppm	ASTM D5185m		776		
CONTAMINANTS		method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>15	4		
Sodium	ppm	ASTM D5185m		0		
Potassium	ppm	ASTM D5185m	>20	<1		
Water	%	ASTM D6304	>0.05	0.004		
ppm Water	ppm	ASTM D6304	>500	41.2		
FLUID CLEANLIN	IESS	method	limit/base	current	history1	history2
Particles >4μm		ASTM D7647	>20000	1144		
Particles >6µm		ASTM D7647	>2500	298		
Particles >14µm		ASTM D7647	>320	24		
Particles >21µm		ASTM D7647	>80	7		
Particles >38µm		ASTM D7647	>20	0		
Particles >71µm		ASTM D7647	>4	0		
Oil Cleanliness		ISO 4406 (c)	>21/18/15	17/15/12		
FLUID DEGRADA	TION	method	limit/base	current	history1	history2

Acid Number (AN)


mg KOH/g ASTM D8045

Report Id: NORDEX [WUSCAR] 05924844 (Generated: 08/16/2023 14:23:09) Rev: 1

Contact/Location: DEVIN LINEHAN - NORDEX



OIL ANALYSIS REPORT







Sample No. Lab Number **Unique Number**

: NX014527 : 05924844

: 10604791

Received Diagnosed

: 15 Aug 2023 Diagnostician

: 16 Aug 2023 : Jonathan Hester 300 SOUTH WACKER DRIVE, SUITE 1500 CHICAGO, IL

US 60606 Contact: DEVIN LINEHAN DLinehan@nordex-online.com

T: (312)386-4124 F: (312)386-7102

Test Package : IND 2 (Additional Tests: KF, PQ) Certificate L2367 To discuss this sample report, contact Customer Service at 1-800-237-1369. * - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)